SCHOOL OF CIVIL ENGINEERING



JOINT HIGHWAY RESEARCH PROJECT

JHRP-76-25


BLOW-UPS ON RESURFACED CONCRETE PAVEMENTS

D. L. Gress





PURDUE UNIVERSITY INDIANA STATE HIGHWAY COMMISSION



Final Report

BLOW-UPS ON RESURFACED CONCRETE PAVEMENTS

T0: J. F. McLaughlin, Director

August 3, 1976 Joint Highway Research Project Revised August 1977

FROM: H. L. Michael, Associate Director

Project: C-36-460

Joint Highway Research Project File: 5-11-15

The attached Final Report is submitted on the JHRP research study entitled "Pavement Blow-ups and Resurfacing". The Report is titled "Blow-ups for Resurfaced Concrete Pavements" and has been authored by D. L. Gress. An Executive Summary report covering the entire project is included. An Interim Report by P. T. Foxworthy, "Statewide Survey of Blowups in Resurfaced Concrete Pavements" was made as JHRP Report No. 3, February 1973. All the reports were prepared under the direction of the principal investigators, Professors W. L. Dolch, C. F. Scholer and E. J. Yoder.

One result of overlaying a concrete pavement that was concluded by the research is that such action increases its probability of having blow-ups distress. The causes are not due to greater temperature or to increase in the coefficient of thermal expansion but due to a general increase in the moisture content and its accompanying expansion combined with the thermal expansion characterization of concrete.

The cooperation of the Indiana State Highway Commission in many phases of this research investigation is acknowledged with sincere appreciation to the many individuals involved.

The report is submitted for approval.

Respectfully submitted,

Tondel 2 Muchael

Harold L. Michael Associate Director

HLM:ms

cc.	1.1	ī	Dolch	V	D	Hoover	_	_	Scholer
CC.									
	R.	L.	Eskew	G.	Α.	Leonards	М.	В.	Scott
	G.	D.	Gibson	R.	F.	Marsh	K.	С.	Sinha
	W.	Н.	Goetz	R.	D.	Miles	С.	Α.	Venable
	Μ.	J.	Gutzwiller	Р.	L.	0wens	L.	Ε.	Wood
	G.	Κ.	Hallock	G.	Τ.	Satterly			Yoder
	D.	E.	Hancher			•			Yoder



Final Report

BLOW-UPS ON RESURFACED CONCRETE PAVEMENTS

bу

David L. Gress Graduate Instructor in Research

Joint Highway Research Project Project No.: C-36-460

File No.: 5-11-5

Prepared as Part of an Investigation
Conducted by

Joint Highway Research Project Engineering Experiment Station Purdue University

in cooperation with the

U.S. Department of Transportation Federal Highway Administration

The contents of this report reflect the views of the author who is responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the official views or policies of the Federal Highway Administration. This report does not constitute a standard, specification, or regulation.

Purdue University West Lafayette, Indiana August 3, 1976 Revised August 1977 218243448 21282500- (384 080845 080 430-8008 218243488 212825000- (384 080845 080 430-8008

Account to the second

The second secon

. Tel Tempor District

,		TECHNICAL REPORT S	TANDARD TITLE PAGE
1. Report No.	2. Government Accession No.	3. Recipient's Catolog	No.
JHRP-76-25			
4. Title and Subtitle		5. Report Date Aug.	1076
BLOW-UPS ON RESURFACED	CONCRETE DAVEMENTS	Revised Aug.	1976
DEON OF SON RESORTACED	CONTRETE ! AVEILENTS	6. Performing Organisat	ion Code
		0.0	
7. Author(s)		8. Performing Organizat	
David L. Gress		JHRP-76-2	
9. Performing Organization Name and Addre	St. Danie of	10. Wark Unit No.	
Joint Highway Research Civil Engineering Bui		11. Contract or Grant N	
Purdue University	. army	HPR-1(13)	
W. Lafayette, Indiana	47907	13. Type of Report and	
12. Sponsoring Agency Name and Address	Compionies	Frank Bank	
Indiana State Highway State Office Building	Commission	Final Repo	ort
100 North Senate Avenu	ue	14. Sponsoring Agency	Code
Indianapolis, Indiana	46204		
15. Supplementary Notes	an with the U.S. Donn	ntmost of Trans	204224
Prepared in cooperation Federal Highway Admin		rument of transp	Jorcacion,
From the Study "Paveme		facing".	
16. Abstract			
crete pavement signific	nis study was to dete	rmine it overla	ying a con-
isolate those variables	s that affect blow-up	distress.	and to
	this study were based		ts of a
statewide survey of ove			
the field testing of a laboratory testing of p			
ments.	davement cores taken	Trom various Inc	liana pave-
The field testing o	f the bare pavement a	nd overlayed par	vement con-
sisted of monitoring de	eformation, temperatu	re and moisture	as a
function of time. Mois			
developed moisture gaug	ing consisted of a mi		
determination of therma	al and moisture prope	rties of selecte	ed pavement
field cores. The micro	scopic testing inclu	ded composition	al analysis,
general physical condition			
ment of infiltration of cores. Coefficients of			
four hour saturation mo	isture states and th	e effect of moi:	sture on
expansion were determin	ned on selected field	pavement cores	using a
special heating chamber measuring system.	r in conjunction with	a sensitive de	rormation
17. Key Words	18. Distribution	Statement	
Pavement, portland ceme	ent concrete, No res	trictions. This	
overlays, blow-up, mair	ntenance, is ava	ilable to the pu	
moisture content, coef.		tional Technical	
chermal expansion	22161	e, Springfield,	Virginia
19. Security Classif. (of this report)	20. Security Classif, (of this page)	21- No. of Poges	22. Price
Unclassified	Unclassified	120	



Executive Summary

BLOWUPS ON RESURFACED CONCRETE PAVEMENTS

The pavement blow-up, be it large or small, results in a bump which is at the very best, uncomfortable and possibly dangerous to vehicular traffic. The term is applied to all bumps caused by compressive stresses resulting from heat, water or other causes and generally occur at a joint or crack. The bump itself occurs when the compressive stress within the pavement causes buckling and/or faulting of the pavement, or when they cause crushing and the broken material is extruded vertically causing a bump in the riding surface. More refined classifications of blow-ups were made in this project's interim report, by Foxworthy.* Blow-ups occur on both bare and on resurfaced pavements. This project primarily concerned itself with resurfaced pavements.

Foxworthy's survey (1) identified the major factors that contribute to blow-ups of resurfaced pavements. These were listed in the summary of that interim report and were as follows:

1. Insofar as influencing blow-ups on resurfaced concrete pavements is concerned, the factors of pavement design, base, and age of the original pavement are all interrelated. The data suggest that present design and construction practices are superior to those of the past in preventing blow-ups.

^{*}Foxworthy, Paul T., Statewide Survey of Blowups in Resurfaced Concrete Pavements", JHRP Report No. 3, February 1973. (An interim report on this project).

E-8x8

Experience Summers

DISCHARGE TO SERVICE AND SERVICE OF SERVICE OF

as are the Edward of Change of a signed of the same of

things we can exist a comment of the comment of the

The artists of all many plants of the relations of the angreens

112 10.00

and the second second second second

Township of the control of the contr

- (a) All other factors being equal, the data indicate that original pavement design is a major factor as a contributor to blow-ups. For example, pavements built between 1941 and 1944 with short joint spacing and no steel depart from the previously established trend of improving performance as design changes were made. These pavements have the highest mean number of blow-ups per mile and the lowest per cent of miles of road with no blow-ups.
- (b) The addition of a granular base beneath concrete pavements in 1946 has substantially improved their performance. This is due, at least in part, to the increased drainage capability provided by the base, thus reducing the moisture present beneath the pavement.
- (c) Blow-up activity increased as the age of the original pavement increased. This trend continued for pavements up to 40 years old with older pavements showing no preference for high or low blow-up occurrence.
- 2. Crushed stone as a coarse aggregate in concrete pavements has shown slightly better performance overall as compared to gravel. However, both types have shown variable performance. The actual source of the material should be given primary consideration when choosing materials.
- 3. Pavements built on subgrades of residual soils showed fewer blow-ups than those on other soil types, and those built through terminal morraines had the highest

- blow-up occurrences. Other soil types showed little differences in performance.
- 4. Weather, winter maintenance (salting and sanding), and soils seem to interact in the district factor, with blow-ups occurring at higher frequencies in the northern portion of the state than in the southern part.
- 5. Paved shoulders are significant in reducing blow-ups.
- 6. Blow-up activity starts very soon after the pavement is overlaid, and the percentage of roads with more than four blow-ups per mile increased with age of the overlay.

A factor which appeared to have little effect on blow-up occurrence was overlay thickness.

Accompanying this project summary is a report by D. L. Gress, "Pavement Blow-ups and Resurfacing", in which similar portions of a concrete pavement were instrumented and measured both with and without an overlay. Cores were taken from additional pavements selected from the comprehensive survey compiled by Foxworthy and careful laboratory measurements made of their coefficient of linear expansion and an analysis made of the concrete's composition.

Temperature and moisture data was obtained and is shown with the measured weather data and with expansion measurements made on the instrumented pavements. These measurements extend thru the total climatic variation experience in Indiana.

Gress's work made use of a simple hence a highly effective and efficient method of measuring dimensional changes of the slab. He also further developed a moisture measuring device



and successfully applied it to enable the concrete's degree of saturation to be internally measured. No existing method was satisfactory. Although his gauges may not be ideal they did give valuable information not otherwise obtainable. Specifically they measured the distribution of moisture within slabs of concrete, both bare and overlaid.

Moisture was shown by Gress's work to be an important factor in the blow-ups behavior of concrete. This contributes some understanding to findings of Foxworthy's field survey and by the observations of others in the field. Gress shows the moisture distribution under an overlay and relates its changes to dimensional changes. This was also established by laboratory measurements.

Temperatures were also measured but similar data has been obtained by other investigators.

In obtaining cores of selected pavements around the state a number of joints were cored, but by no means all of the joints were cored. The findings showed that considerable infiltration had occurred in some joints. No statistical correlation could be found between blow-ups and the infiltration of joints. It should be pointed out that Gress's last conclusion, "Infiltration cannot be demonstrated to be significantly related to blow-up distress", should be taken as it is stated and not construed to mean that such a relationship does not sometimes exist. A much more extensive coring program would be required to clarify this question.

The total effect of overlaying a concrete pavement is to increase its probability of having blow-ups distress. The causes

to sergel 7/ The real ods what he will be an all and a serge of the se

as developed by Gress are not due to greater temperature or to increase in the coef. of thermal expansion. The principal cause appears to be a general increase in the moisture content and its accompanying expansion combined with the thermal expansion characterization of the concrete.

The overlaid pavements became critically saturated for a considerable time in the winter. The consequence of this on cement paste and aggregate as it undergoes the freeze-thaw cycles of a winter are obvious. A concrete may have been resistant in the lower degree of saturation, yet may fail at the larger degree saturation. D-cracking coarse aggregates would especially be subject to this acceleration of deterioration due to overlaying.

It is believed, by the principal investigators, that a substantial number of the small blow-ups, such as are called high joints in overlaid pavements, are caused by the deterioration of the concrete under the combination of compressive stresses, and aggravated freeze-thaw exposure due to the increased moisture resulting from overlaying the pavement.

A goal of this project was to make recommendations for corrective procedures as well as diagnostic methods to indicate the likelihood of blow-ups occurring.

The results are not definitive enough to allow quantitative measurements to be judged as an accept or reject system for evaluating a potential pavement for overlay. Instead the common nemesis of pavements, moisture, must be considered. Everything that will reduce moisture will tend to reduce the likelihood



of blow-ups. This was shown by Foxworthy's survey of Indiana pavements. A further aid in reducing blow-ups is the survey itself which should be kept up and will identify material which are more prone to blow-ups. This is commonly done by experience but the documentation should help make it more generally acceptable and understood.

of blow ups. This was shown by Porworthy S. spread to Todiate pureweater. A corrher and in Toducing binweaps, (a the infrag pureweater. A corrher and in Toducing binweaps, (a the infrag and will infellectly and which should be been ups and will infellectly dune by experience are excepted to blow-ups. This is commonly dune by experience but the determinant on about 2 (etc., only if core governilly accept-

ACKNOWLEDGEMENTS

The author wishes to express his appreciation to Dr. William L. Dolch and Dr. Charles F. Scholer for their invaluable guidance and support during the conduct of this research. The statistical consultation form Dr. Virgil Anderson is very much appreciated.

The assistance in field site preparation, field testing, sample preparation and laboratory testing from Mr. Max Anthis and Mr. Chip Locke is greatly appreciated.

The author extends special thanks to his wife, whom without her this study would not have been possible, for her assistance in testing, data reduction, typing and for her endless patience throughout the course of the study.

- 111/1/2010/00/2010/2014

TABLE OF CONTENTS

																1	Page
LIST OF	TABLES	• •			•	•			•	•		•	•	•	•	٠	v
LIST OF	FIGURES	• • •			•	•			•	•		•	•	•	•	•	vii
PREFACE.					•	•			•	•		•	•	•		•	х
INTRODUC	TION .	• •	• •							•		•		•	•	•	1
LITERATU	RE REVI	EW.			•				•	•		•	•	•	,	•	3
FIELD TE	STING.	• •			•	•	• •		•	•		•	•	•	•	•	7
Sit Mea Pro	e Selec e Prepa suremen Defor Tempe Moist cedure Data a Analy Verti Horiz Defor Coeff	ration to Teomatic rature Collegies cal ! ontain matic	on. chni on. re. ecti Mois l Mo	ique	es.	/ar:	iat:	ion.				•	•	•	•	•	9 10 11 17 17 25 38 44 49 58
LABORATO			• •		•	•		• •	•	•	• •	•	•	•	•	•	72 72
	ing Sch t Core Compo Physi Infil	Analy sition	ysis on. Cond	i	on.	•	• •	• •	• •	•		•	•	•			72 75 76 79 96
	rmal Ex Linea Heati Tripo Sampl Testi Test sture E	pans: r Var ng Cl d . e Suj ng Te Cores	ion riak hamb ppor echr	ole er. rt a	Dii	ffe: Ex	ren ten	tial	l Tr	an d	sfo	rme	er •	•	•	•	102 104 105 107 108 110 112



TABLE OF CONTENTS (Con'd.)

	Page
Test Cores	116
SUMMARY	120
Field Testing	120 122
CONCLUSIONS	
CONCLUDING COMMENTARY	. 126
LIST OF REFERENCES	. 128
APPENDIX	. 131
Appendix A	128
Field Testing Error of Measurement	140
Mojsture Gauge Design	140
Appendix C	154
Regression Analysis	154
Appendix D	160
Field Data	167
Cherry Lane Moisture Data.	
Appendix F	
Daily Precipitation	174
Appendix G	. 177 . 177

		,	


LIST OF TABLES (Con'd.)

Appen Tabl						Page
A6.	Ball System Data	•	•	•		. 164
A7.	Ball System Data		•	•		. 166
A8.	Average Daily Degree of Saturation	•		•	•	. 167
А9.	Purdue Agronomy Farm Daily Precipitation	•	•		•	. 174
A10.	Test Core Information					. 177



LIST OF FIGURES

Figure		Pa	age
1.	Details of the Ball System	•	12
2.	Deformation Measurement Position of the Ball System		14
3.	Location of Ball Systems Bl Through B8		15
4.	Base Lengths Between Side Mounted Balls	•	16
5.	Typical Moisture Gauge	•	20
6.	Typical Moisture Probe		21
7.	Wiring Diagram for the Determination of Degree of Saturation	•	23
8.	Temperature Change Versus Degree of Saturation for Moisture Probe 3-B Gauge Number 1		26
9.	Temperature Change Versus Degree of Saturation for Moisture Probe 3-0 Gauge Number 4		27
10.	Temperature Change Versus Degree of Saturation for Moisture Probe 3-B Gauge Number 3		28
11.	Temperature Change Versus Degree of Saturation for Moisture Probe 1-B Gauge Number 4	•	29
12.	Calibration Curve for Moisture Probe 1-B	•	30
13.	Calibration Curve for Moisture Probe 2-B	•	31
14.	Calibration Curve for Moisture Probe 3-B	•	32
15.	Calibration Curve for Moisture Probe 1-0	•	33
16.	Calibration Curve for Moisture Probe 2-0	•	34
17.	Calibration Curve for Moisture Probe 3-0	•	35
18.	Location of Moisture Probes		36



LIST OF FIGURES (Con'd.)

Figure	9					Pa	age
19.	Degree of Saturation Versus Time for Position 3, Gauges 1 and 2					•	39
20.	Degree of Saturation Versus Time for Position 3, Gauges 3 and 4						39
21.	Degree of Saturation Versus Time for Position 3, Gauges 1 and 2		•		•	•	40
22.	Degree of Saturation Versus Time for Position 3, Gauges 3 and 4			•	•	•	40
23.	Degree of Saturation Versus Time for Position 3, Gauges 1 and 2		•	•	•		41
24.	Degree of Saturation Versus Time for Position 3, Gauges 3 and 4		•	•	•	•	41
25.	Degree of Saturation Versus Time for Position 3, Gauges 1 and 2		•		•		42
26.	Degree of Saturation Versus Time for Position 3, Gauges 3 and 4		•		•	•	42
27.	Average Degree of Saturation Versus Time for the Overlayed Pavement	•	•	•	•	•	47
28.	Average Degree of Saturation Versus Time for the Overlayed Pavement	•	•	•		•	47
29.	Average Degree of Saturation Versus Time for the Overlayed Pavement	•	•	•		•	48
30.	Average Degree of Saturation Versus Time for the Overlayed Pavement	•	•		•	•	48
31.	Precipitation and Strain Versus Time		•		•		50
32.	Precipitation and Strain Versus Time		•				50
33.	Precipitation and Strain Versus Time	•	•	•		•	51
34.	Degree of Saturation, Precipitation and Strain Versus Time		•	•	•	•	51
35.	Degree of Saturation, Precipitation and Strain Versus Time	•		•	•	•	52

LIST OF FIGURES (Con'd.)

Figure	∋	F	age
36.	Degree of Saturation, Precipitation and Strain Versus Time	•	52
37.	Degree of Saturation, Precipitation and Strain Versus Time	•	53
38.	Precipitation and Coefficient of Thermal Expansion Versus Time	•	63
39.	Degree of Saturation, Precipitation and Coefficient of Thermal Expansion Versus Time	•	65
40.	Apparent Thermal Coefficient Versus Relative Humidity	•	68
41.	Apparent Thermal Coefficient Versus Degree of Saturation	•	69
42.	Details of Heating Chamber	•	105
Append Figur			
Al.	Pavement Warping for a Negative Temperature Gradient		133
A2.	An Element Subjected to a Negative Temperature Gradient		133
А3.	The Relationship Between the Vertical Deformation V and Angle ϕ	•	135
А4.	The Relationship Between the Error Term and the Vertical Deformation	•	135
A5.	Theoretical Temperature Change Versus Water/ Cement	•	147
A6.	Theoretical Temperature Change Versus Aggregate Content	•	148
A7.	Theoretical Diffusivity Versus Water/Cement	•	150
A8.	Theoretical Diffusivity Versus Aggregate Content	٠	151

PREFACE

This research project included an extensive statewide survey of rigid pavements which had received one or more flexible, bituminous, overlays. The information resulting from the survey was subjected to analysis to identify factors which are important contributors to blow-ups in resurfaced pavements. It was also used to identify particular pavements for further investigation and sampling for detailed laboratory investigation.

The statewide survey was reported in an interim report by P. T. Foxworthy (10), "Statewide Survey of Blow-ups in Resurfaced Concrete Pavements", J.H.R.P. Report No. 3, February 1973.

A laboratory investigation was also made upon samples obtained by coring at field locations determined from the data of the statewide survey. This work is reported in detail in this Final Report, pp. 72-118.

Aside from the performance aspects attributable to the materials and conditions of the pavement, an important part of a rigid pavement's volume change will always occur due to thermal and moisture changes. The extent is related to the materials involved but the characteristic behavior occurs irregardless of the material. The field testing was to measure the change in characteristic behavior, over a season, of a section of pavement part of which had overlay and part bare. Insofar as



possible, these were the only variables. Moisture and temperature gradient were measured as were the physical dimensions and position of the pavements involved. This did not directly relate to the statewide survey but was important to the full understanding of the behavior of concrete pavement slabs, both bare and with overlay. This work is reported in this Final Report, pp. 7-71.

·	

INTRODUCTION

Blow-ups of portland cement concrete pavements have been a serious problem encountered by the Indiana State Highway Commission and other highway departments for many years. These blow-ups are sometimes hazardous to the road user and are detrimental to the riding quality of the pavement. They also require expensive corrective maintenance.

Blow-ups continue to develop after a concrete pavement is resurfaced with a bituminous overlay. There are some grounds, also, for a belief that blow-up activity is increased by the resurfacing, although the problem has not been investigated prior to this investigation.

The use of bituminous overlays on portland cement concrete has been common practice for upgrading deteriorating pavements. With the completion of the Interstate Highway System many miles of pavement will eventually have to be resurfaced. Although overlaying is extensively used in maintenance, its complete success is open to speculation for certain pavements, because of the blow-up problem as well as other difficulties, such as reflection cracking and freeze-thaw deterioration under the resurfacing. These problems are naturally interrelated, because cracking increases the access of water to the underlying pavement,



and aggregates that give blow-up susceptible pavements are also frequently poor in freeze-thaw behavior.

and aggreenmen that rave plow-up susceptible pavements are

LITERATURE REVIEW

The causes of blow-ups are somewhat speculative. The slab expands longitudinally. This causes it to hump up or arch at some weak point, generally a transverse joint or crack. The rise is from a fraction of an inch to more than a foot, and there is cracking and shattering dependent on the extent and character of the expansion and on other conditions, such as slab strength. Frequent vertical or alignment curves appear like bends in a steam pipe, to take up the expansion without disruptive movement (1)*.

"The most frequent occurrence of blow-ups is when a hot day is followed by a rainy night succeeded by another hot day, causing both temperature and moisture expansion". Although this statement (1) was published fifty years ago, it has significance today. Surveys have shown that blow-ups occur predominately in mid-afternoon at a temperature in excess of 90°F which period was usually preceded by varying amounts of rain (2,3,4,5,6).

Extensive field performance surveys and studies (2,7,8,9) of concrete pavements have shown correlation to exist between coarse aggregates used in the concrete and

^{*}Numbers in parentheses refer to references listed in the List of References.

WITT SHALL DESIGNATION

estate and a second and a secon

na filoza lata expertuto de tempor en como esperto de la del malda berrada anoma a avada. Por extenda el catalesa el catalesa

Sumbers In preintheate refer to reference listed in the

the blow-up performance of the pavements. However, other studies (5,10) have not shown such a correlation, but the possibility could not be disproven.

To date, work in this area has been qualitative and empirical and has not resulted in an understanding of the blow-up mechanism. It is known that temperature and moisture content of the concrete affect blow-ups, but the quantitative relationships of these variables as they affect the expansion of concrete is not well understood.

The coefficient of thermal expansion of the concrete is obviously a predominate factor. It is proportional to the individual coefficients of the components of the concrete (the cement paste, the fine aggregate, and the coarse aggregate) and to their volume proportion in the concrete. A small overall coefficient is, presumably, desirable in preventing blow-ups. The small amount of work to date (11) suggests, at least for Indiana aggregates, that limestone coarse aggregates with relatively small thermal expansion coefficients are more associated with blow-up failures than are gravels with silicious components of a higher coefficient. These findings are obviously contrary to the simple assumptions of the expansion process.

With respect to the hardened cement paste component, the thermal coefficient has been shown to be related to the water content, with intermediate values giving a higher coefficient than that of either dry or saturated pastes

(12,13). Although the thermal coefficient of cement and concrete has been shown to be some function of moisture and temperature (14,15,16,17,18,19,20), the relationships between all these factors and the susceptibility of a pavement to blow-ups is still largely conjectural.

It is possible that all pavements are potentially susceptible to blow-ups. Perhaps if the temperature and moisture content were increased to some critical level the pavement would leave its dormant state and become just as bad concerning blow-up performance as the pavements with the now condemned aggregates. This possibility is the result of previous work (22,23) concerning an increase of blow-ups with the advent of concrete resurfacing. The cause was probably not due to an increase of temperature, since the new surface was of similar material to the old, but the moisture content may have increased. A flowing film of water was found by Gotham and Lord (23) at several places between the two layers of concrete. This was noticed when normal maintenance required cutting a section in the pavement.

Another variable just as important for some pavements as those already mentioned is the functioning of the joints. One premise is that blow-ups occur because incompressible material lodges in open joints and cracks and restricts subsequent expansion and causes disruptive stresses (21). Poor performance of joint sealant compounds is suspected of



being a primary cause of surface infiltration (6). Field inspections of pavement blow-ups have shown the presence of joint infiltration (3,4). This action may be responsible for many blow-ups, but it does not explain why a pavement can become blow-up susceptible after being resurfaced. Therefore joint failures do not themselves preclude other mechanisms also coming into play. The whole picture is probably one of combined influences playing their parts.



FIELD TESTING

The coefficient of thermal expansion of a porous material is a function of its moisture content. Meyers has shown the coefficient of thermal expansion of a cement paste to vary by a factor of two for some relative humidity between zero and 100 percent, where the coefficients are approximately equal (12). The maximum increase in the coefficient of thermal expansion occurs at approximately 75 percent relative humidity. Since cement paste is a porous material and a component of concrete, the thermal expansion of concrete is a function of its moisture content. Most aggregates are not porous compared with cement paste; therefore, their coefficients of thermal expansion are not a function of moisture content. In light of the above, the aggregate component lessens the effect of changing moisture content on the thermal expansion of concrete. Assuming a linear law of composition holds for concrete, the coefficient of thermal expansion $\alpha_{\boldsymbol{m}}$ can be calculated as

 $\alpha_T = (\% \text{ Paste x } \alpha_{TP} + \% \text{ Aggregate x } \alpha_{TA})/100$ where α_{TP} is the coefficient of thermal expansion of the paste and α_{TA} is the coefficient of thermal expansion of the aggregate component.



If α_{TA} = $\frac{1}{2}$ α_{TP} , which is a reasonable assumption, the above equation expressed in terms of α_{mA} becomes

$$\alpha_{\rm T}$$
 = (% Paste x $2\alpha_{\rm TA}$ + % Aggregate x $\alpha_{\rm TA}$)/100

A typical concrete pavement contains approximately 20 percent paste and 80 percent aggregate. These values result in a concrete with a coefficient of thermal expansion of

$$\alpha_{\text{T}}$$
 = .20 x 2 α_{TA} + .80 α_{TA} = 1.20 α_{TA}

A maximum coefficient is expected at approximately 70 to 80 percent relative humidity and can be calculated by substituting the α_{TP} value at this relative humidity into the equation. This gives

$$\alpha_{\text{TMax}}$$
 = .20 x 4 α_{TA} + .80 α_{TA} = 1.60 α_{TA}

The maximum percent difference of the coefficient of thermal expansion of concrete to be expected is

$$Max Δα_T \% = \frac{1.60 α_{TA} - 1.20 α_{TA}}{1.20 α_{TA}} × 100$$

$$= 33\%$$

Therefore the maximum difference that is expected for a typical concrete pavement under the most adverse moisture conditions is 33 percent.

A premise of increased blow-up activity for an overlayed pavement versus a bare pavement is that the asphalt

forms a barrier on the surface of the pavement, causing an internal moisture increase. This increased moisture state not only increases the coefficient of thermal expansion, a maximum of perhaps 33 percent as noted above, but will also increase the internal strain of moisture expansion. The net result is an increase in the length of the pavement slab and also an increased response to length change caused by fluctuating temperatures. This in turn reduces the joint openings if the joint were originally open, or increases the stress level within the slab if the joint openings were closed or filled by infiltration. As shown by Euler's column buckling analogy, when the stress level reaches a certain level a blow-up can occur. Therefore it is possible these conditions could result in a pavement blow-up.

An approach to analyzing such a premise is to observe an actual pavement system. Variables to monitor include change in length, temperature, and moisture content for both an overlayed pavement and a bare pavement under common environmental conditions.

Site Selection

Ideally to test the above premise two pavement slabs should be selected that abut each other, in order to maintain constant environmental conditions. This was not possible because traffic was to be maintained as normal and an asphalt wedge was required to create a reasonably smooth

transition between the bare section and the overlayed section.

An area was found that contained two relatively long uncracked slabs separated by ample distance to build a satisfactory asphalt transition wedge. For all practical purposes, the slabs were close enough together to be subject to the same environmental conditions. This area was found on State Road 126, locally known as Cherry Lane, in West Lafayette, Indiana. State Road 126, hereafter referred to as Cherry Lane, was constructed in 1957. The design specifications required the slab to be eight inches thick, construction joints only, no steel except for tie bars, and they allowed the use of salvage material for the base material. Concrete mix specifications were in accordance with the 1952 Standard Specifications for Road and Bridge Construction and Maintenance of the Indiana State Highway Commission. These specifications required six bags of cement per cubic yard, with a maximum of 5.5 gallons of water per bag of cement, slump between one and three inches and an air content between three and six percent.

Site Preparation

Preparations toward making Cherry Lane a test road began in the Spring of 1973. Four expansion joints were cut across the full width and depth of the pavement to make the slabs independent of each other and of the remaining pavement not included in the test section. These joints

were four inches wide. A pre-formed expansion material was placed in each. This was done by the Indiana State Highway Commission and was in accordance with their maintenance procedures for relieving pressures in bridge approach pavements. During July 1974 one test slab was overlayed with 1.25 inches of surface mix asphalt, while the other was left bare.

Measurement Techniques


Deformation

Several methods of measuring strains in the field were possible, but no single method had the necessary properties of long term stability, accuracy and simplicity. Therefore a new method of measuring strains was devised. This method, referred to as the ball system, is capable of measuring vertical as well as horizontal deformations, as a function of environmental changes. The ball system proved to give reliable measurements of deformations with sufficient accuracy to calculate a coefficient of thermal expansion.

Appendix A contains an analysis of the maximum error to be expected for the ball system method of measuring deformation.

Details of the ball system are shown in Figure 1. This system consists of three one-quarter inch diameter stainless steel balls, two mounted on top of a four foot rod driven in the subgrade near the edge of the pavement and one mounted on the edge of the concrete pavement. The construction










balls were pressed into a threaded rod, which was screwed into the rod and pavement blocks, and secured in place with a lock nut. The rod cap block was tightly screwed into the top of the four foot rod. The pavement block was held in place by a lead anchor rigidly secured at the centerline of the pavement's edge. An aluminum base plate was used to separate the pavement block from the pavement to compensate for surface irregularities and oversized anchor holes. All parts were made of stainless steel except for the aluminum base plate and the four foot steel rod. Longitudinal deformation corresponds to a change in Position 1 as shown in Figure 2. Vertical deformation likewise corresponds to a change in Position 2 were measured using a micrometer with a non-rotating shaft and capable of reading to 0.0001 inches.

A one-half inch thick steel plate supported by two sections of channel iron driven into the subgrade provided ample protection of the ball system from traffic. The top steel plate was covered with shoulder material to minimize the possibility of vandalism.


Three ball systems were installed along the edge of each test slab, one on each end and one in the center. One additional system was placed on the slab closest to the test slabs. These were labeled Bl through B8 and are as shown in Figure 3. The base distances between the side mounted balls for the bare and overlayed test sections are shown in Figure 4.













Temperature

Temperature must be recorded along with slab deformation to calculate a coefficient of expansion. Thermocouples were selected for measuring temperatures. Thermocouples were chosen as the mode of temperature measurement over other methods because of their reliability, durability, ease of installation, and simplicity of use. When used in conjunction with an electronic reference junction, an accuracy of 0.1°F was achieved. Temperature probes were constructed in the laboratory, then grouted into a one inch hole cored into the test slabs. These probes were located midway between the pavement's edge and centerline and five feet from the expansion joints. No attempt was made to measure temperature within the asphalt. Lead wires were protected from traffic by placing them in a one inch deep groove cut into the pavement with a portable concrete saw, then sealed with an epoxy resin. This method has shown no sign of deterioration to date, and is expected to last indefinitely. Five thermocouples were placed in each probe, spaced at two inches center-to-center with the top and bottom being located approximately 1/16 of an inch from the surface.

Moisture

In conjunction with temperature and deformation a measurement of moisture content and especially changes in the moisture content would be very meaningful in determining

the effect of overlaying a concrete pavement. An extensive literature search did not reveal a reliable method of obtaining such measurements (24). The nuclear density method of moisture measurement can be used to detect changes in moisture content and was selected as a possible method to investigate.

The nuclear density gauge in principle should be a useful method, but unfortunately its bulb of influence is very shallow in the back-scatter mode and is therefore highly influenced by the moisture state near the surface. It was shown that this area does not change in moisture content drastically except immediately after a rain shower and therefore gave a poor indication of change in moisture for the whole slab. An alternative method was devised. The principle of this alternative method is simple in nature and is based on the fact that the thermal conductivity, heat capacity and density of a porous material are dependent upon its moisture content. Lentz and Monfore (25) used much the same principle in their method for the determination of thermal conductivity of concrete.


A gauge was constructed by placing a thermocouple in the center of a 3/4 inch diameter loop of number 30 gauge nichrome wire and then surrounding both with mortar.

Twenty such gauges were fabricated at one time by using a modified one-by-one-by-eleven inch bar mold. Special emphasis was given to compaction of the mortar by using a

This was done to minimize the number of entrapped air bubbles, which would have an effect on the calibration of the gauge. The one-to-one mortar mix used was made of shrinkage compensating cement and graded Ottawa sand with a water cement ratio of 0.35. This mix was selected on bases of stability and sensitivity, as described in Appendix B.

Ten such gauges were thus cast one inch apart in each eleven inch bar. These bars were cured in a fog room for a minimum of 28 days. The gauges and their surrounding mortar block were cut from the bar and were ground on a polishing wheel until their thicknesses were approximately 1/4 inch, as shown in Figure 5. These gauges were then tested and those that responded similarly to the same degree of saturation were selected for extensive calibration.

An experiment revealed that if the gauges were surrounded by at least one inch of mortar, any size effect of the mortar block would no longer be present. Therefore, it was decided to place the gauges in three inch diameter by eight inch high cylinders, hereafter referred to as moisture probes. Four gauges were placed in each moisture probe with a 2½ inch center-to-center spacing, as shown in Figure 6. The mortar used in the moisture probes was made using a Type I cement with the same mix proportions as the moisture gauge mix.









FIGURE 6. TYPICAL MOISTURE PROBE



Each gauge was calibrated, at various moisture states, by applying a constant current of one ampere across the heater wires for a period of 30 seconds and recording the maximum temperature rise. This corresponds to an average total energy input of 60 joules. The zero percent degree of saturation was defined as the moisture state that exists after three days of oven drying at 105°C. The 100 percent degree of saturation was defined as the moisture state that exists after vacuum saturation for three to four hours plus an additional submersion under water for twenty-four hours. The various intermediate points were determined by drying and resaturating the moisture probes. The degree of saturation was assumed to be uniformly distributed throughout the volume of the probes. The calibration data are presented in Appendix C.

The wiring diagram for the moisture probe testing is given in Figure 7. The Omega, Model No. CJ, temperature reference junction converted the thermocouple's electromotive force to a 32°F reference and was recorded directly from the Fluke digital voltmeter, Model No. 8300 A, in millivolts direct current. The Topaz invertor, Model No. 250-GWD, supplied power to the digital voltmeter, the Heath kit timer Model No. N-15, and the Lambda power supply, Model No. LP411FM.

These moisture probes were calibrated against their own degree of saturation and not the concrete's in which



	1		

they were placed. It was necessary to assume that the degree of saturation of the probe was equal to the degree of saturation of the concrete. This seems reasonable in light of a recent publication (26) that shows while the moisture content for a tested mortar is not equal to that of a concrete subjected to the same moisture conditions, their degrees of saturation are approximately equal.

The calibration data, temperature change versus the degree of saturation, were plotted for each gauge and visually analyzed. An inflection point was found to occur at a degree of saturation of 85 percent to 95 percent on all the gauges except three. The gauges having an inflection point were broken into two sections by visually drawing two best fit lines. The best fit regression equations were determined for each line. Those data points located in the near vicinity of the intersection of the two lines were included as common data for both regression equations. inflection point was assumed to be the intersection of the two regression equations. A single regression equation was determined over all of the data for the three gauges without apparent inflection points. Regression equations determined by this method assume a linear relation between temperature change and degree of saturation. This has recently been shown to be a valid assumption (26) and is not a restriction. The regression equations, of each gauge with an inflection point were expressed by singularity functions so that one



equation could be used to express the entire calibration range.

Typical regression equations and calibration data are shown in Figures 8 through Figure 11. Gauge 1 of moisture probe 3-B, shown in Figure 8, is typical of all the two curve type gauges. Gauge 4 of moisture probe 3-O, shown in Figure 9, is typical of the three single curve gauges. The equations of gauge 3 and gauge 4 of moisture probe 3-B and moisture probe 1-B, shown in Figure 10 and Figure 11, describe the data with the least accuracy of all the gauges. Even though these are the least accurate, their regression R² values are both larger than 0.91. Data with regression R² values of this magnitude are commonly used with sufficient accuracy for most engineering applications.

The calibration curves of the six moisture probes are shown in Figures 12 through Figure 17.

The moisture probes were installed in the test slabs during July 1974. Their locations and identifications are shown in Figure 18. The distance measured from the pavement's edge to Position 1, Position 2 and Position 3 are two, five and eight feet, respectively.

Procedure

Data Collection

Investigation of the test section was initiated during the Summer of 1973. The testing procedure through the Fall







FIGURE 8. TEMPERATURE CHANGE VERSUS DEGREE OF SATURATION FOR MOISTURE PROBE 3-8 GAUGE NUMBER I





TEMPERATURE CHANGE VERSUS DEGREE OF SATURATION FOR MOISTURE PROBE 3-0 GAUGE NUMBER 4 FIGURE 9.





FIGURE 10. TEMPERATURE CHANGE VERSUS DEGREE OF SATURATION FOR MOISTURE PROBE 3-8 GAUGE NUMBER 3





TEMPERATURE CHANGE VERSUS DEGREE OF SATURATION FOR MOISTURE PROBE 1-8 GAUGE NUMBER 4 FIGURE 11.




FIGURE 12. CALIBRATION CURVE FOR MOISTURE PROBE 1-B




FIGURE 13. CALIBRATION CURVE FOR MOISTURE PROBE 2-8




FIGURE 14. CALIBRATION CURVE FOR MOISTURE PROBE 3-B




FIGURE 15. CALIBRATION CURVE FOR MOISTURE PROBE 1-0




FIGURE 16. CALIBRATION CURVE FOR MOISTURE PROBE 2-0







FIGURE 17. CALIBRATION CURVE FOR MOISTURE PROBE 3-0





of 1973 was to measure Position 1 and Position 2 of each ball system and the temperature of the five gauges in the temperature probe simultaneously. These data were taken for each ball system as quickly as possible to minimize temperature variation within the concrete slab. The order of testing was to measure the ball systems B5, B7, B6 and B8 of the overlayed section first, then Bl, B2, B4 and B3 of the bare section, all in the order as listed. The moisture probes were installed in July 1974, and the procedure since then has been as above with the following exceptions: neously with each set of ball measurements temperatures were recorded from each gauge in the temperature moisture probes. The moisture readings were taken immediately after completion of the ball measurements starting with Gauge 1 of moisture probe 1-B and ending with Gauge 4 of moisture probe 3-B. A second set of data were then taken in the same order to assure repeatibility. Occassionally repeatibility was not obtained, and the testing with the individual gauge was continued until the ΔT 's agreed within $0.09^{\circ}F$. values were then averaged, and the degree of saturation was determined by using the appropriate linear regression equation. Similarly, moisture readings were taken on four gauges of moisture probes 1-0, 2-0, and 3-0 of the overlayed section.

To calculate a coefficient of expansion it is necessary to have two independent measurements of temperature and



length. Therefore it was necessary to take two sets of data each day. In order to minimize errors of measurement, an attempt was made to take the readings at as large a temperature difference as possible.

The ball system data, length change, and average temperatures are presented in Appendix D. The average temperatures during the 1973 testing period were determined by taking the average of the five thermocouples. During the 1974 testing period the average temperatures were determined by averaging the four thermocouples of Position 3. The corresponding degree of saturation measurements are given in Appendix E.

Data Analysis

Vertical Moisture Variation

The six moisture probes were monitored over a period of one year, from July 1974 through June 1975. The average daily degree of saturation of each gauge is given in Appendix E. The lead wires of Gauges 2 and 3 of moisture probe 1-B and 2-B respectively were destroyed during installation and data collection was impossible. However, the remaining twenty-two gauges functioned properly throughout the test period. Position 3 data were complete for both the bare pavement and the overlayed pavement and will be used for comparisons of moisture states.

Figures 19 through Figure 26 show the degree of saturation of Positon 3 for the various gauges for the bare




FIGURE 19. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES I AND 2




FIGURE 20. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES 3 AND 4






FIGURE 21. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES I AND 2




FIGURE 22. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES 3 AND 4






FIGURE 23. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES I AND 2




FIGURE 24. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES 3 AND 4






FIGURE 25. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES I AND 2




FIGURE 26. DEGREE OF SATURATION VERSUS TIME FOR POSITION 3, GAUGES 3 AND 4

pavement and overlayed pavement as a function of time. general trend is for the overlayed pavement always to have a higher degree of saturation for a given vertical position, and the overlayed pavement shows a smaller seasonal variation with time than the bare pavement. Vertical moisture gradients always exist in the overlayed pavement. general the degree of saturation increases from the top to the bottom of the pavement. Except for the winter season the bare pavement shows an approximately constant degree of saturation throughout its depth. Gauge 1 of the bare pavement as will be shown later is more dependent upon weather conditions than Gauge 1 of the overlayed pavement. overlayed pavement tends to hold moisture and not dry out as readily as the bare pavement. Both pavements surpassed the level of critical saturation with respect to freezing and thawing durability during the test period. The overlayed pavement obtained this critical moisture state during the winter season when freezing temperatures were prevalent, whereas the bare pavement did not obtain this critical moisture state until late spring when freezing conditions were no longer prevalent. When these critical moisture states occurred Gauge 1 had the lowest degree of saturation and Gauge 4 the highest degree of saturation whereas prior to this time Gauges 1 and 2 were approximately equal and had a higher degree of saturation than Gauges 3 and 4 which were also approximately equal.



With the exception of Gauge 1 of the bare pavement all gauges had degrees of saturation in excess of 100 percent on June 10, 1975. In accordance with the calibration procedure 100 percent degree of saturation was the moisture state after three to four hours of vacuum saturation plus an additional twenty-four hours of submersion under water. However, it is entirely possible that conditions could exist in the pavement causing a higher absorption of water than occurred in the calibration of the gauges thus giving degrees of saturation in excess of 100 percent. However, the relative values are the important ones, and they will still be yalid.

Horizontal Moisture Variation

The average daily degree of saturation for Position 1 through Position 3 of the overlayed pavement and Position 3 of the bare pavement are given in Table 1. These data were calculated by taking the average of all four gauges for each test day. Figures 27 through Figure 30 show the effect of horizontal position on degree of saturation as a function of time. Moisture gradients occur horizontally as well as vertically. Through February 1975 Position 3 had the highest degree of saturation, Position 2 the intermediate degree of saturation and Position 1 the lowest degree of saturation. At this time the horizontal moisture gradient across the pavement was approximately five percent per foot, increasing from the side to the middle.



TABLE 1

AVERAGE DAILY DEGREE OF SATURATION

OVERLAYED-BARE	POSITION 3	5. 1	t	ω.	۴.	2.9	4.0	4.0	4.5	8.9	6.1	0.9	5.2	8.3	8.1
BARE	POSITION 3	89.3	79.8	85.3	88.8	80.2	84.0	82.4	81.1	82.0	79.9	78.1	78.0	4.67	80.1
	POSITION 3	88.8	4.67	86.5	88.5	83.1	88.0	86.4	85.6	88.8	86.1	84.1	83.2	87.7	88.2
OVERLAYED	POSITION 2 %	83.7	71.4	81.7	82.5	4.67	82.9	81.3	82.6	82.9	80.3	77.1	78.1	82.2	82.3
	POSITION 1	82.8	72.6	77.3	78.8	76.0	78.8	77.1	77.4	9.67	73.3	72.1	73.7	9.97	78.5
	DATE	7-18-74	7-22-74	7-25-74	7-26-74	7-27-74	7-28-74	7-29-74	7-30-74	8-01-74	8-02-74	8-05-74	8-12-74	8-13-74	8-14-74



TABLE 1, CONT.

-BARE	8 N															
OVERLAYED.	POSITION 3	8.1	7.5	12.1	10.6	18.2	16.9	12.1	19.2	25.4		22.4		2.2	7.2	13.1
BARE	POSITION 3	80.8	78.2	7.77	4.77	8.69	66.3	6.97	79.2	72.0		0.97	11 11 0000	81.6	87.5	104.9
	POSITION 3	88.3	90.3	4.06	87.9	88.0	83.2	88.9	4.86	5.76	97.2	98.3	101.5	83.8	L.46	118.0
OVERLAYED	POSITION 2	82.4	85.0	85.5	84.9	*80.0	79.5	85.1	85.2	81.6	97.2	81.7	6.96		9.06	106.5
	POSITION 1	75.8	6.97	74.5	73.8	7.07	67.3	75.0	75.6	7.47	84.1	81.6	83.6		8.06	117.2 ge 1
	DATE	8-16-74	8-17-74	8-21-74	10-06-74	10-16-74	10-20-74	10−30−14	1-13-75	2-19-75	2-26-75	3-05-75	3-19-75	4-16-75	5-05-75	6-10-75 *without Gauge 1




FIGURE 27. AVERAGE DEGREE OF SATURATION VERSUS TIME FOR THE OVERLAYED PAVEMENT




FIGURE 28. AVERAGE DEGREE OF SATURATION VERSUS TIME FOR THE OVERLAYED PAVEMENT






FIGURE 29. AVERAGE DEGREE OF SATURATION VERSUS TIME FOR THE OVERLAYED PAVEMENT




FIGURE 30. AVERAGE DEGREE OF SATURATION VERSUS TIME FOR THE OVERLAYED PAVEMENT




During the early spring, conditions caused the gauges to go through a period of fluctuation. As of June 10, 1975 Position 2 had the lowest degree of saturation and Position 3 remained the highest at which time all were in excess of 100 percent degree of saturation. This horizontal moisture gradient was also approximately five percent per foot. Unlike the moisture state during February, this diminished from the pavement side to Position 2 and then increased towards the middle. This seems reasonable in light of the heavy rainfall that occurred in that time period.


Deformation and Strain

One premise of pavement blow-ups is pavement growth which could occur by increased moisture content when a pavement is overlayed. The deformations were monitored from August 1973 through June 1975. These data, with the daily precipitation occurring in the proximity of the test site, and degree of saturations are included in Figures 31 through Figure 37.


The pavement strains were based on the original measurements taken three days after the pavement was overlayed, and they are corrected for temperature by assuming average values for the coefficients of thermal expansion.


These data are given in Table 2. The average daily precipitation occurring within the proximity of the test site during July 1973 through June 1975 are given in Appendix F.
















FIGURE 35. DEGREE OF SATURATION, PRECIPITATION AND STRAIN VERSUS TIME





FIGURE 36. DEGREE OF SATURATION, PRECIPITATION AND STRAIN VERSUS TIME





APRIL 75
TIME (DAYS)

FIGURE 37. DEGREE OF SATURATION, PRECIPITATION AND STRAIN VERSUS TIME



TABLE 2

TEST PAVEMENT DEFORMATION AND STRAIN

OVERLAYED-BARE MICRO- STRAIN EB-EO	I	- 2.1	3.5	-10.6	0.5	3.7	0.1	7.6	7.8	0.0	3.6	3.8	3.5
MICRO- STRAIN ^E O		1.9	-4.5	-2.5	1.7	-11.1	1.5	8.1	9.0	-3.9	-3.3	-6.8	1
1ATTON 1104 A _{LB7}		-14	9	54	61	917	19	120	121	77	42	71	42
DEFORMATION IN X10 ⁴ A _{LB5}		28	-25	-70	64-	-123	-57	h9-	70	-3.04	-102	-118	-79
MICRO- STRAIN EB		0.4	0.8-0	8.3	1.2	-14.8	1.4	-1.6	-7.2	-3.9	6.9-	-10.6	-3.6
DEFORMATION IN x10 ⁴ LB2 A _{LB4}		6	-35	7 7	-14	-25	58	917	30	43	33	20	55
DEFOR IN ^A LB2		35	-16	10	22	-71	64-	-56	92-	-68	-78	-89	-78
DAYS AFTER OVERLAYED	0	ħ	2	19	20	56	30	31	39	0 ħ	911	Lη	52
рате	8-25-73	8-29-73	8-30-73	9-13-73	9-14-73	9-20-73	9-24-73	9-25-73	10-03-73	10-04-73	10-10-73	10-11-73	10-16-73



TABLE 2, CONT.

OVERLAYED-BARE	43.8	48.4	47.2	6.44	43.2	48.1	1°6ħ	53.4	29.5	12.7	19.5	19.9
°0	32.0	25.5	28.1	33.4	29.4	32.3	33.3	33.9	14.9	9.5	9.01	19.4
overlayed ^A lb7	817	807	845	842	837	837	926	857	783	774	897	898
$^{\Lambda}_{ m LB5}$	-594	-629	649-	-610	-629	-612	-624	-621	-679	-710	-823	-733
°B	-11.8	-22.9	-19.1	-11.5	-13.8	-15.8	-16.4	-19.5	-14.3	-3.5	6.8-	- 5
BARE ^A LB4	724	680	899	702	069	684	673	<i>1</i> 29	789	856	924	992
$^{\Lambda}_{ m L_{B2}}$	-800	-828	-791	922-	622-	-786	-778	-783	-881	878	-981	-995
DAYS AFTER OVERLAYED	342	345	352	353	354	356	357	361	417	431	909	h 2 9
DATE	8-02-74	8-05-74	8-12-74	8-13-74	8-14-74	8-16-74	8-17-74	8-21-74	10-16-74	10-30-74	1-13-75	6-10-75



TABLE 2, CONT.

OVERLAYED-BARE	5.1	10.3	9*11	2,8	4.3	8.1	14.4	6.2	29.1	29.1	L• ክካ	9° ħħ	6.04	6.04	41.8
	-3.6		-2.4	2.0	1.4	-5.2	2.2	-1.6	32.6	32.6	35.0	37.9	30.5	32.5	29.5
OVERLAYED *AL B7	69	80	78	89	110	94	122	112	845	845	871	698	844	836	817
*^LB5	η6-	96-	96-	06-	-101	-130	-107	-122	-617	-617	-627	-605	-632	609-	-614
E _B	-8.7	-12.5	0.7-	-3.0	-2.9	-13.3	-12,2	-7.8	3.5	3.5	1.6-	1.9-	-10.4	4.8-	-12.6
BARE $^{\Delta}$ LB4	24	21	39	44	39	33	36	43	745	245	729	731	731	744	725
$^{\Delta}$ LB2	-81	-102	-84	19-	-58	-119	-115	-93	-722	-722	-791	η <i>LL</i> -	-798	-798	908-
DAYS AFTER OVERLAYED	53	54	09	61	119	89	75	83	327	329	335	336	337	338	339
DATE	10-17-73	10-18-73	10-24-73	10-25-73	10-28-73	11-01-73	11-08-73	11-16-73	7-18-74	7-20-74	7-56-74	7-27-74	7-28-74	7-29-74	7-30-74

The degrees of saturation for the bare pavement and the overlayed pavement are based upon the average values of Position 3 as given in Table 1.

During the time period August 1973 through November 1973 the strains were approximately equal to each other and on the average tend to be negative, which implies shrinkage when compared to the base length. The precipitation occurring during the spring of 1974 caused both pavements to undergo expansion. The overlayed pavement on July 19, 1974 had a strain of approximately thirty micro-strains more than the bare pavement. At this time the bare pavement had a strain of approximately four micro-strains, thus showing little change when compared to its base length. During the month of August 1974 the difference between the overlayed pavement and the bare pavement obtained a maximum of about fifty micro-strains. At this point the overlayed pavement showed an expansion of about thirty micro-strains while the bare pavement showed a contraction of about twenty microstrains.

The relationship between precipitation, degree of saturation and strain followed a general pattern. The gauges respond directly to precipitation, especially precipitation in excess of one inch, and to extended dry periods. The strain also followed this relationship, with the bare pavement being more sensitive to precipitation changes.



The strain in the overlayed pavement decreased from thirty-four micro-strains to nine micro-strains from August through October 1974, whereas during this same period the bare pavement increased from negative twenty micro-strains to negative four micro-strains.

The trend from October 1974 through June 1975 was to increase the expansion of the overlayed pavement from nine micro-strains to nineteen micro-strains while during the same time period the bare pavement increased from negative four micro-strains to negative one micro-strain.

The general seasonal trend was for the overlayed pavement to show an expansion, while the bare pavement had a tendency to be equal to or less than its original base strain, thus showing a contraction. The overlayed pavement showed its greatest expansion during the summer months, a period critical to blow-up activity. Although this strain is not of sufficient magnitude by itself to cause a blow-up to occur, it could certainly be, and probably is a contributing factor to the blow-up mechanism. A strain of this magnitude corresponds to a temperature change of approximately ten degrees.

Coefficient of Thermal Expansion

The analysis of error presented in Appendix A concludes that a restriction must be imposed on the temperature differences between deformation measurements. This restriction is necessary in order to minimize the error of



measurement. A conservative maximum error of approximately ten percent can be achieved by restricting the temperature change between measurements to greater than about six degrees. A time interval limitation must also be imposed to minimize the testing error. A long time interval between deformation measurements could affect the coefficient of expansion due to the effect of a change in moisture over such an interval. Obviously, if the moisture content increases considerably an expansion caused by moisture movement will be compounded with that caused by temperature change. The end result would be an apparent increase in the coefficient of thermal expansion. Conversely a reduction in moisture content would cause an apparent decrease in the coefficient of thermal expansion. The effect of moisture change was minimized by analyzing only those data taken on the same day or late one night and early the next day. This method does not eliminate all error but should minimize it, because field moisture states, although continuously changing, do take time to change significantly.

Coefficients of expansion were calculated from data satisfying the above restrictions and are presented in Table 3 and Table 4. Temperature differences between measurements are included in Table 3. The second table also contains the average daily degree of saturation for moisture probes 3-B and 3-O and the ratios of the differences in the coefficients of thermal expansion and the degrees of



TABLE 3

COEFFICIENT OF THERMAL EXPANSION OF TEST SITE

DATE		PERATURE ANGE ^O F	C	DEFFICIENT EXPANSION	OF THERMAL
	BARE	OVERLAYED	BARE	OVERLAYED	OVERLAYED-BARE
10-04-73	- 9.6	-8.2	4.62	4.59	-0.03
10-10-73	-10.2	-8.7	3.27	3.45	0.18
10-11-73	11.7	10.4	3.98	4.11	0.13
10-16-17-73	-10.9	-10.1	4.64	4.52	-0.12
10-17-18-73	11.8	9.0	3.85	4.34	0.49
10-24-73	11.7	11.6	4.52	4.05	-0.47
10-24-25-73	-14.9	-14.2	4.27	3.93	-0.34
10-25-73	13.9	12.8	4.43	3.98	-0.45
10-25-73	-10.6	-8.7	3.90	3.83	-0.07
10-28-73	-8.9	-7.6	3.32	4.51	1.19
11-01-73	6.2	6.7	5.02	4.70	-0.32
11-16-73	8.8	8.5	3.40	4.15	0.75

FERM

THE TEST OF BURRANCE ASSESSED TO CHECKERS

INCIDED OF THE PROPERTY.

THUTAKIBANT

MONG

B-AB-CHYALISYO TONALAND W YEAR ON ATTOYOUR BARE

TELLO TO THE TELLO THE TEL

TABLE 4

THERMAL AND MOISTURE TEST SITE DATA

$SLOPE=\Delta\alpha_{\rm T}/\Delta_{\rm DS}$ $/^{\rm O}F\%DSx106$		017	.027	063	400.	004	008	012	031	051	034	011	015
COEFFICIENT OF THERMAL EXPANSION / Px106	OVERLAYED-BARE $\Delta \alpha_{\mathrm{T}} = \alpha_{\mathrm{T}} - \alpha_{\mathrm{T}}$	07	.12	38	.02	03	07	10	25	38	33	13	19
CIENT OF THE	OVERLAYED $^{\alpha}\mathrm{T}_{\mathrm{O}}$	4.30	3.70	3.59	3.74	3.59	3.99	3.94	3.57	3.66	3.68	3.81	3.81
COEFFI	BARE (α_{T}	4.37	3.58	3.97	3.72	3.62	4.06	40.4	3.82	40.4	4.01	3.94	4.00
SATURATION ENT	OVERLAYED-BARE ADS=DS _O -DS _B	4.2	4.5	0.9	5.2	6.8	8.3	8.2	8.1	7.5	8.6	12.1	12.7
DEGREE OF SAT PERCENT	OVERLAYED DS _O	86.0	85.6	84.1	83.2	85.5	87.7	88.0	88.2	88.3	89.3	90.3	4.06
DEGR	BARE O'DSB	81.8	81.1	78.1	78.0	78.7	19.4	79.8	80.1	80.8	79.5	78.2	77.7
DATE 1974		7-29-30	7-30	8-05	8-12	8-12-13	8-13	8-13-14	8-14	8-16	8-16-17	8-17	8-21




measurements for the bare pavement and the overlayed pavement were 21.2 and 18.2°F respectively for the data presented in Table 4. The coefficients were analyzed statistically as paired observations to test the hypothesis that there is a difference in the coefficient of expansion between the bare pavement and the overlayed pavement. The data of 1974 are significantly different at the 0.01 level.

The average coefficients of expansion for the two test periods were 4.10 and 3.93x10⁻⁶/°F for the bare pavement and 4.18 and 3.78x10⁻⁶/°F for the overlayed pavement. The average degrees of saturation for the bare pavement and the overlayed pavement were 79.4 percent and 87.6 percent, respectively. The 1973 data imply that the coefficient of expansion for the overlayed pavement was on the average approximately two percent larger than that of the bare pavement, which is certainly not of significant magnitude to be the main factor in the blow-up mechanism. Conversely, the 1974 data imply the opposite, namely that the bare pavement on the average had a coefficient approximately four percent larger than the overlayed pavement.

Figure 38 shows the relationship between coefficient of thermal expansion, precipitation and time for the bare pavement and the overlayed pavement for the 1973 testing period. The average values of the coefficients of thermal expansions are 4.10 and 4.18×10^{-6} for the bare pavement





PRECIPITATION AND COEFFICIENT OF THERMAL EXPANSION VERSUS TIME FIGURE 38.



and the overlayed pavement, respectively. The corresponding standard deviations are 0.57 and $0.37 \times 10^{-6} / {}^{\circ}F$.

The coefficients of the bare pavement and the overlayed pavement follow a general trend of increasing with rainfall and decreasing during dry periods. The higher standard deviation of the bare pavement's coefficient implies a higher sensitivity to climatological conditions than the overlayed pavement.

Figure 39 shows the relationship of degree of saturation, precipitation and coefficient of thermal expansion as a function of time for the 1974 testing period. Both the bare pavement and the overlayed pavement followed the same general trend as during the 1973 testing period, increasing after precipitation and decreasing during periods of dryness. The degrees of saturation followed a similar trend. The average value of the coefficients for the bare pavement and the overlayed pavement were 3.93 and 3.78xl0⁻⁶/°F, respectively. These data are significantly different at the 0.01 level. During this time period the average degrees of saturation for the bare pavement and the overlayed pavement were 79.4 percent and 87.6 percent, respectively.

The coefficients determined on July 29, 1974 and July 30, 1974 had average values of 4.34 and $3.64 \times 10^{-6} / ^{\circ}F$. This result corresponds to a decrease of 20 percent within a period of less than one day. While their reduction is in agreement with the general trend, it cannot be explained in



FIGURE 39. DEGREE OF SATURATION, PRECIPITATION AND COEFFICIENT OF THERMAL EXPANSION VERSUS TIME



terms of changing degree of saturation or precipitation. This sudden reduction was common to both the bare pavement and the overlayed pavement. This effect can be normalized by analyzing the data with respect to each other. Table 4 gives the change in the coefficient of thermal expansion and degree of saturation and their ratio for each test day. This ratio, $\Delta\alpha_{\rm T}/\Delta DS$, is the slope of the coefficient of thermal expansion versus degree of saturation curve. With the exception of two values this was always negative, implying that an increase in degree of saturation causes a decrease in the coefficient of thermal expansion. The average value of this slope is calculated by

$$\frac{3.78 - 3.93}{87.6}$$
 x10⁻⁶/°F%DS

$$= -0.018 \times 10^{-6} / {}^{\circ} F\%DS$$

The significance of the negative sign is to imply that the moisture content of the overlayed pavement was higher than the maximum of their thermal expansion versus relative humidity curve.

The significance of the magnitude and sign of this experimentally determined slope was evaluated by analyzing independent data. Portland Cement Association Bulletin 90 (27) shows the relationship between apparent thermal expansion coefficient and relative humidity for a concrete made with quartz aggregate. The test pavements were made of a local aggregate composed of approximately equal amounts of igneous and sedimentary particles and would be expected to



behave similar to the quartz aggregate concrete. points were extrapolated from the bulletin and are given in Figure 40. Conversion from relative humidity to degree of saturation can be accomplished by assuming typical properties for the paste component of the concrete. To accomplish this conversion data were taken from Portland Cement Association Bulletin 22 (28), Table A-12, page 321. The cement had a water cement ratio of 0.433 and was cured for 180 days before being tested. These data were used to develop the relationship between degree of saturation and relative humidity. Assuming the pavement concrete had a corrected water cement ratio of 0.433 and the aggregate has zero absorption, the apparent thermal coefficient can be expressed as a function of the degree of saturation, as presented in Figure 41. The apex of the curve has shifted to the left and occurs at a degree of saturation of around 47 percent. The best fit slope from 45 percent to 100 percent degree of saturation assuming a linear relationship is $-0.017x10^{-6}/{}^{\circ}F\%DS$ which compares well with the average experimental value from the pavements of $-0.018 \times 10^{-6} / {}^{\circ}$ F%DS.

The effect of increasing the water cement ratio of the concrete on the curve of coefficient of thermal expansion versus degree of saturation is to decrease the value of degree of saturation at which the maximum coefficient occurs. Since the lowest recorded degree of saturation for






FIGURE 40. APPARENT THERMAL COEFFICIENT VERSUS RELATIVE HUMIDITY






FIGURE 41. APPARENT THERMAL COEFFICIENT VERSUS DEGREE OF SATURATION



the overlayed pavement was 67.3 percent, the coefficient would always decrease with increasing degree of saturation.

The experimental slope, -0.018×10^{-6} / $^{\circ}$ F%DS, can be used to predict the maximum and minimum coefficients of thermal expansion to be expected over the possible range of degree of saturation. A maximum coefficient of thermal expansion of 4.47×10^{-6} / $^{\circ}$ F would occur at a degree of saturation of 50 percent and a minimum value of 3.55×10^{-6} / $^{\circ}$ F at 100 percent degrees of saturation.

Expected degree of saturation can be determined using the experimental slope and a measured value of coefficient of thermal expansion. The predicted average degrees of saturation for the bare pavement and the overlayed pavement are 70 percent and 66 percent, respectively, for the 1973 testing period. Considering the amount of precipitation before and after the pavement was overlayed, the season of the testing period, and the time period after being overlayed, these values seem reasonable. These values also imply that an extended period of time is required for an overlayed pavement to increase its degree of saturation. To date, the overlayed pavement has a 13 percent higher degree of saturation than the bare pavement.

In conclusion it seems that overlaying a pavement increases its degree of saturation and concomitantly decreases its coefficient of thermal expansion. The time required for a significant change in the moisture state



of the overlayed pavement is a function of precipitation and, to date, is still increasing after two years, having a 13 percent higher degree of saturation to date than the bare pavement. This corresponds to a decrease in the coefficient of thermal expansion of about 6 percent.

Summarizing the overlayed pavement reached a level of critical saturation when freezing temperatures were prevalent. The increase of moisture due to overlaying a pavement caused an expansion equal to the same effect as a ten degree temperature rise. The horizontal moisture gradient was 5 percent per foot. Except during periods of high precipitation, the degree of saturation increased from the pavement's side to the middle portion of the pavement. The middle portion of the pavement. The slope of the thermal coefficient of expansion and degree of saturation curve over the normal range of moisture encountered in the field was -0.018x10⁻⁶/F⁰/%D.S.

The occurrence of critical saturation of overlayed pavements would lead one to expect more deterioration in freezing and thawing in the colder portion of the state. This was found to be true. However, it also could be caused by infiltration or deflections caused by heavier traffic. In all probability, all three factors contribute to the demise of quality concrete adjacent to cracks and joints under overlays.

The quality of the aggregate in freeze-thaw exposure is of considerable concern. A marginally D-cracking aggregate, for instance, would become more saturated and undergo more distress after overlaying than when it was bare.



LABORATORY TESTING

Coring Scheme

The first objective of this study was to collect information concerning the blow-up performance of overlayed rigid payements under the authority of the Indiana State Highway Commission. Information was compiled on more than 3400 miles of rural highway. These data included the blow-up distress, as categorized during the 1971 field survey, and construction data for each test section. These data were extensively analyzed as reported by Foxworthy (10).

Previous work of Woods, Sweet and Shelburne (2) implies that the source and type of the coarse aggregate have a high correlation with blow-up performance for bare concrete pavements. The field survey data were statistically analyzed to see if such a correlation also exists for overlayed pavements. The analysis concluded, on the average, that pavements made with gravel aggregates showed poorer blow-up performance than those made with crushed stone and, unlike the original work of Woods, Sweet and Shelburne, that little significance could be placed on the individual source of aggregate. The first conclusion seems reasonable if significant emphasis is placed on the coefficient of thermal expansion, since concrete made of gravel



would be expected to have a higher coefficient of thermal expansion. Statistical insignificance of source also seems reasonable in light of the wide spread blow-up performance of overlayed concrete pavements.

Although the field survey did not show a significant difference among the various sources of aggregate analyzed, the possibility of such a relation could not be ignored in the method of core selection.

A generalized correlation between blow-up distress and composition of aggregate, if reliable, would be beneficial in determining the method of core selection. Such correlations were determined by relating blow-up distress to chemical composition and rock type composition. The compositional data compiled by the Indiana Geological Society and the Indiana Limestone Producers Association were determined from samples obtained in the general vicinity of the aggregate sources used in the pavement test sections. Correlation regression R² values of 0.30 and 0.06 were found for the limestone and gravel sources, respectively. Unfortunately these correlation equations were not capable of relating blow-up performance to aggregate type with any reliability, and were not used as a basis of core selection. This does not imply that a reliable correlation does not exist, because in order to accomplish this analysis it was necessary to assume the test sections were constructed with aggregate of the same composition and type as the samples



taken from the general area of the aggregate sources.

In the absence of any known relation of blow-up distress it was decided to select the sections to be cored by observing the information compiled in the State blow-up survey (10). Concrete age, blow-up distress, route number, number of overlays, age of last overlay and source of coarse aggregate were given consideration in selecting the test sections to be cored.

Bare pavements were also included in the coring sections in addition to the overlayed sections considered in the State survey of blow-ups. Special emphasis was given to the location of those sections which were partially over-layed, as this would give a valuable indication of the effect of overlaying a pavement. Test sections of bare concrete pavement which had been overlayed with portland cement concrete were also selected to evaluate the effect of a non-asphalt overlay. Unfortunately every section had also been overlayed at least one additional time with asphalt; in fact, one section on U.S. 20 had a total thickness in excess of 24 inches and could not be sampled with conventional coring equipment.

Visual observations were made of the selected sections, and the specific locations to be cored were determined. The basis of determining the position of coring within each section was to core in the vicinity of a blow-up distressed area, and also within an area of zero blow-up distress. The



locations cored on those sections without blow-ups were determined primarily on a basis of traffic safety.

The effect of infiltration was also investigated during the coring process for certain selected sections by taking cores over joints and cracks.

A total of 176 test cores were obtained from selected test sections throughout the six districts of the state.

Appendix G gives detailed information for each test core.

The Indiana State Division of Materials and Testing of the Indiana State Highway Commission kindly supplied the coring rigs and personnel to obtain the test cores.

Test Core Analysis

The test cores were given an identification number and were then stored until tested. The first digit of the identification number corresponds to the Indiana State Highway District in which the test section was located. The districts, labeled one through six, are: LaPorte, Fort Wayne, Crawfordsville, Greenfield, Vincennes and Seymour, respectively. The remaining digits in the identification number chronologically numbers the test cores in the order in which they were taken.

Physical measurements were taken and recorded on each test core as it was received in the laboratory. These include number and thickness of overlays, concrete thickness, aggregate types, and presence of freeze-thaw cracks and scaling cracks. In addition to physical measurement,



each test core was photographed.

Polished sections were examined for composition, general physical condition, and infiltration. Surfaces were prepared by cutting a slab from the center of each test core and then polishing one side of the slab. The polished sections were approximately four inches wide and as long as the original test core was high. A technique was developed to repair those samples that broke during the coring or cutting processes. This worked well on clean breaks and maximized the polished areas on friable, weak samples.

Composition

Compositional analysis was determined on selected test cores in accordance with the modified point count method of C457 (29). These data are presented in Table 5. With the exception of air content, they are approximately equal.

This is as expected, since all test cores were from pavements that have approximately equal specified compositions.

The average percentages for paste, coarse aggregate and fine aggregates were 22.4 percent, 46.5 percent and 27.9 percent, respectively. Test cores 3-49, 3-51, 3-52 and 3-54 were the test cores obtained in preparing the Cherry Lane test site for moisture probes BP1, BP3, OP1 and OP3, respectively. The average values of air, paste, coarse aggregate and fine aggregate for the bare test pavement were 4.4, 23.7, 49.3 and 22.8% respectively, and for the overlayed test

TABLE 5


COMPOSITIONAL ANALYSIS OF TEST CORES

SAMPLE			AGGRE	GATE
NUMBER	AIR	PASTE	COARSE	FINE
1-1	1.1	26.4	41.5	31.0
3-6	1.7	20.8	53.3	24.2
3-21	1.0	23.9	45.6	29.4
3–22	1.1	23.4	41.8	33.6
3-25	1.7	20.1	43.1	35.1
3-27	0.9	20.1	51.2	27.8
3 – 28	4.5	19.9	38.8	36.8
3 - 30	5.4	21.7	41.4	31.4
3-32	2.4	20.5	47.9	29.2
3-35	3.0	21.1	49.1	26.8
3 - 36	3.7	28.0	38.6	29.8
3-40	3.5	26.3	49.7	20.6
3-41	2.7	24.1	51.1	22.1
3-45	6.8	26.3	43.0	23.9
3-46	5.6	25.2	32.0	37.2
3-47	5.4	22.4	46.6	25.5
3–48	4.7	20.1	48.3	26.9
3-49	5.6	23.8	48.1	22.5
3 - 51	3.1	23.5	50.4	23.0
3 – 52	4.5	18.2	52.5	24.8
3-54	4.3	22.9	46.8	26.0
5-19	2.4	16.1	63.3	18.2



TABLE 5, CONT.

SAMPLE NUMBER	AIR	PASTE	AGGREGATE COARSE FIN			
6-3	0.7	17.3	59 .7	18.2		
6-17	1.7	24.8	32.6	40.9		



pavement 4.4, 20.6, 49.7 and 25.4%, respectively.

These data were statistically analyzed to determine if significant difference exist among the concrete composition components as related to blow-up distress. The air content variable F-ratio versus F-test statistic was 2.46 versus 2.95 at the 0.10 level of significance. Although this analysis did not show a significant difference among the variables, it gives an indication of the relative significance of the variables. The regressional analysis of these data shows the effect of air content to be a negative correlation with blow-up distress. This implies that as percent of entrained air increases, the level of blow-up distress decreases.

Physical Condition

Polished sections of selected test cores were visually examined under a microscope to determine their physical conditions. The presences of air entrainment, lime deposits in voids and cracks, aggregate type, presences of freezethaw cracks, aggregate cracks, the overall intensity of cracks in the concrete and scaling cracks were noted for each tested polished section. These data with source of coarse aggregate, if known, along with any comments are presented in Table 6. The last digit of the aggregate source identification number, 1, 2, or 3, represents aggregates composed of gravel, crushed limestone or slag, respectively. The remaining numbers correspond to a

TABLE 6

PHYSICAL CONDITION ANALYSIS

COMMENTS	Poor aggregate,	Asphalt in cracks.	Very dense paste,	Dolomite aggregate.	Poor aggregate.	Dolomite aggregate; excellent concrete.	Porous limestone; Dolomite aggregate,	Natural asphalt in aggregate vugs.	Limestone and banded Dolomite aggregate; cracks radiate from aggregate.	Poor sedimentary aggregate.
AGGREGATE SOURCE	56012	56012	56012	56012	56012	93052	74051	74051	09031	89021
CONCRETE	Severe	Severe	Few	None	Severe	None	Few	None	Severe	Severe
CKS AGGREGATE	Severe	Severe	Moderate	None	Severe	None	None	None	Moderate	Moderate
CRACKS FREEZE AG THAW	Yes	Yes	No	No	Yes	No	No	No	Yes	Yes
SCALING	No	Yes	No	No	Yes	No	Yes	No	Yes	Yes
AIR LINE AGGREGATE TYPE	જ	જ	જ્ઞ	8	જ	જ	જ	৪	જ્ઞ	S.
R LIME	Yes	Yes	Yes	s No	Yes	Yes	Yes	Yes	Yes	Yes
AI	No	No	No	Yes	No	No.	No	No	N O	No
CORE	1-1	1-3	1-7	198	1-12	1-18	1-19	1-21	1-23	2-1



TABLE 6, COVT.

COMMENTS	All light colored aggregate particles cracked.	All light colored aggregate particles cracked; cracks full of lime.	All light colored aggregate particles cracked; cracks full of lime.	Small quantity of large size coarse aggregate,	Small quantity of large size coarse aggregate.	Limestone and Dolomite aggregate; poor limestone; poorly compacted.	Limestone and Dolomite aggregate.
AGGREGATE SOURCE	27022	27022	27022			01012	90012
CONCRETE	Severe	Severe	Severe	Severe	None	Moderate	Severe
CRACKS ZE AGGREGATE W	Severe	Severe	Severe	Severe	None	Moderate	None
CRA FREEZE THAW	Yes	Yes	Yes	Yes	No	Yes	Yes
SCALING	No	No	No	Yes	No	No	No
AGGREGATE TYPE	જ્ઞ	જ	જ	GR	GR	প্ত	ន
AIR LIME	Yes	Yes	Yes	Yes	Yes	Yes	Yes
AIF	No	No	No	No	No	No	No
CORE	2-4	2-5	5-6	2-7	5-9	2-10	2-11



TABLE 6, CONT.

COMMENTS	Similar to Core 2-11, except sand is igneous type.	Very dense paste.	Excellent concrete, except for cracked aggregate particles.	Dense paste.		Cracks radiate from aggregate.	Some perpendicular cracks radiating from coarse aggregate; concrete in excellent condition.	Very porous areas around aggregate particles.	Interconnecting shrinkage cracks.
AGGREGATE SOURCE	90012		87021	89021	11062	11062	09041	09041	17060
CONCRETE	Severe	None	Pew	Few	Moderate	Moderate	None	Severe	Severe ction.
CKS AGGREGATE	None	None	Moderate	None	Moderate	Few	None	Few	Moderate -thaw prote
CRACKS FREEZE AG THAW	Yes	No	No	No	Yes	Yes	No	Yes	Yes r freeze
SCALING	Yes	No	No	No	Yes	No	o N	No	Yes for prope
AIR LIME AGGREGATE TYPE	જ્ઞ	GR	જ્ઞ	GR	GR	GR	GR	E	3-6 No Yes GR&CS Yes Yes Moderate Seve Insufficient air-entrainment for proper freeze-thaw protection.
LIME	Yes	*Yes Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes t air-
AIR	No	*Yes	No	No	No	No	No	No	No
CORE	2-12	2-15	2-16	2-17	3-1	3-5	3-4	3-5	3-6



TABLE 6, CONT.

CONTENTS	Exceptionally good concrete.	Porous aggregate particles have radi- ating cracks into paste.	Porous aggregate.	Banded sedimentary aggregate shows parallel cracks extending into paste.	Top one-third shows extensive parallel cracking.	Porous aggregate parti- cles all cracked.	Porous aggregate parti- cles all cracked.	Poorly compacted.	Limestone with chert.
AGGREGATE SOURCE	23021 23031	23021 23031	79011 83031	79011 89031	23011	23011	23011	49101	67012
CONCRETE	None	Severe	Severe	Moderate	Severe	Severe	Severe	Few	Severe
CKS AGGREGATE	None	Few	Moderate	Few	Severe	Moderate	Moderate	Few	Severe
CRACKS FREEZE AG THAW	No	Yes	Yes	o O	Yes	Yes	Yes	No	Yes
SCALING	Yes	Yes	Yes	SN SN	Yes	Yes	Yes	No	Yes
AIR LIME AGGREGATE TYPE	GR&CS	GR&CS	GR	GR.	æ	GR	GR	GR	જ
LIME	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes
AIR	No	No	No	No	No	No	S _O	No	No
CORE	3-7	3-12	3-13	3-15	3-16	3-17	3-18	3-19	3-21



TABLE 6, CONT.

CONFIENTS	Limestone with chert; paste porous near surface.	Top one-third extremely deteriorated; lower two-thirds in good condition.	Many parallel cracks.	Many parallel cracks.	Poorly compacted; good concrete.	Very poorly compacted.	Excellent condition; sufficient air entrainment.	Sufficient air entrain- ment; 3 or 4 surface shrinkage cracks.	Interconnected cracks near surface.
AGGREGATE SOURCE	67012	67012	84011	84011	83011	83011	61051	61051	83011
CONCRETE	Severe	Severe	Moderate	Severe	None	None	None	None	None
CRACKS ZE AGGREGATE CONCRETE W	Severe	Severe	Moderate	Severe	None	None	None	None	None
CRA FREEZE THAW	Yes	Yes	Yes	Yes	No	No	No	No	No
SCALING	Yes	Yes	Yes	Yes	No	No	No	No	Yes
AIR LIME AGGREGATE TYPE	જ્ઞ	S	GR	GR&CS	GB.	GR	GR	GR	GR
R LIME	Yes	Yes	Yes	Yes	Yes	Yes	Yes No	Yes No	Yes
AI	No	No	No	No	No	No	Yes	Yes	No
CORE	3-22	3-24	3-25	3-27	3-28	329	3-30	3-31	3-32



TABLE 6, CONT.

COMMENTS	Extensive surface cracking.	Two small surface shrinkage cracks.	Large aggregate is limestone.	Two surface shrinkage cracks.	Two surface shrinkage cracks.	Two surface shrinkage cracks.	Porous paste.	Good concrete.	Good concrete.	Good concrete.	Porous paste.
AGGREGATE SOURCE	83011	67022	67022	83011	83011	86011	11062	79011	79011	79011	79011
CONCRETE	Moderate	Few	Severe	None	None	None	None	None	None	None	None
CRACKS ZE AGGREGATE W	Moderate	None	Severe	None	None	None	None	None	None	None	None
CRA FREEZE THAW	Yes	No	Yes	No	No	No	No	No	No	No	No
SCALING	Yes	Yes	Yes	No	NO	No	Yes	No	No	No	No
AIR LIME AGGREGATE TYPE	GR	GR&CS	GR&CS	GR	89	GR	GR	GR	GR	GR	GR.
AIR LIME	No Yes	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	Yes No	*Yes No
CORE	3–33	3-35	3-36	3-40	3-41	3-43	3-45	3-46	3-47	3-48	3-49

*Insufficient air entrainment for proper freeze-thaw protection.

TABLE 6, CONT.

COMMENTS	Large arrount of entrapped air; porous paste.	Porous paste; two interconnected cracks near bottom.	Porous paste; good concrete.	Two surface shrinkage cracks.	Several perpendicular cracks throughout section.	Parallel cracks through smaller size aggregate particles.	Cracks radiate from aggregate particles.	Soft aggregate particles show excessive cracks.
AGGREGATE SOURCE	79011	79011	79011	79011	49151 89031		89031 49151	89031 49151
CONCRETE	None	Few	None	None	Реw	Severe	Moderate	Severe
CKS AGGREGATE	None	None	None	None	None	мем	Moderate	Moderate
CRACKS FREEZE AG THAW	No	No	No	No	No	Yes	Yes	Yes
SCALING	No	No	No	Yes	No	Yes	Yes	O N
AIR LIME AGGREGATE TYPE	GR	GR	GR	GR	æ	GR	æ	æ
AIR LIME	Yes No	*Yes No	*Yes Yes	*Yes No	Yes No	No Yes	*Yes Yes	*Yes Yes
CORE	3–50	3-51	3–52	3-54	4-2A	4-2B	4-7	4-10

*Insufficient air entrainment for proper freeze-thaw protection.



TABLE 6, CONT.

COMPENTS	Poor gradation of coarse aggregate.	Poor gradation of coarse aggregate.	Many parallel cracks.	Small section size; severely deteriorated concrete.	Small section size; severely deteriorated concrete.	Limestone coarse aggregate severely cracked; extensive parallel cracking.	large parallel cracks near bottom and top; coarse aggregate parti- cles extensively cracked.
AGGREGATE SOURCE	21011	21011	09012	09012	09012	09012	
CONCRETE	Severe	Severe	Severe	Severe	Severe	Severe	Moderate
CRACKS FREEZE AGGREGATE THAW	Severe	Severe	Severe	Severe	Severe	Severe	Moderate
CRACKS FREEZE AG THAW	Yes	Yes	Yes	Yes	Yes	Yes	Yes
SCALING	Yes	Yes	Yes			No	ON O
AIR LIME AGGREGATE TYPE	GR	GR	GR	જ	જ	GR&CS	GR
LIME	Yes	Yes	Yes	Yes	Yes	Yes	Yes
AIR	No	No	No	No	NON	No	S O
CORE	4-13	4-14	4-17	4-18	4-19	4-20	4-22

TABLE 6, CONT.

COMMENTS	Limestone and Dolomite aggregate; large parallel cracks; limestone particles cracked.	Several parallel cracks; two surface shrinkage cracks.	Some coarse aggregate cracks, but do not run into paste.	Limestone and Dolomite aggregate; very porous concrete.	Surface shrinkage cracks; coarse aggregate particles cracked, but do not run into paste.	Poorly compacted.
AGGREGATE SOURCE	60012	60012	60012	13012	13012	84011 84031
CONCRETE	Few	Moderate	None	Moderate	None	None
CRACKS FREEZE AGGREGATE THAW	Moderate	Severe	Few	Few	Moderate	None
CRACKS FREEZE AG THAW	Yes	No	N O	Yes	No	No
SCALING	No	No	No	Yes	NO	No
AGGREGATE TYPE	ક	প্ত	જ	જ	જ	Æ
AIR LIME AGGREGATE TYPE	*Yes No	Yes No	Yes No	*Yes Yes	*Yes Yes	Yes Yes
CORE	5-2	5-3	5-5	5-8	5-10	5-12

*Insufficient air entrainment for proper freeze-thaw protection.

TABLE 6, CONT.

	ınkage			ack ne cles not	s ent	ste;	ıcks	clon.
COMMENTS	One surface shrinkage crack.	Poor aggregate.	Poor aggregate.	One parallel crack near bottom; some aggregate particles cracked, but do not run into paste.	Shrinkage cracks visible; excellent concrete.	Excellent concrete; large amount of entrapped air.	Top parallel cracks infiltrated with asphalt.	Excellent condition.
	One su crack.	Poor a	Poor a	One pan hager baggreg cracker	Shrinkage visible; concrete.	Excelllarge entrag	Top para infiltra asphalt.	Excel
AGGREGATE SOURCE	60012	47112		47112				
CONCRETE	None	Severe	Severe	Moderate	None	None	Few	None
KS AGGREGATE	None	Severe	Severe	Moderate	None	None	None	None
CRACKS FREEZE AG THAW	No	Yes	Yes	Yes	No	No	Yes	No
SCALING	No	No	Yes	ON	No	No	Yes	No
AIR LIME AGGREGATE TYPE	GR	GR	GR	GR	GR	GR	GR	GR
AIR LIME	Yes No	*Yes Yes	No Yes	*Yes No	Yes No	Yes No	Yes No	Yes No
20日程	5-14	5-19T	5-19B	5-20	5-21	522	5-23	5-24

*Insufficient air entrainment for proper freeze-thaw protection.



TABLE 6, CONT.

COMMENTS	Coarse aggregate mostly limestone; one crack in large Colitic limestone particle.	Small section; parallel bands near top surface.	Aggregate extremely cracked; severe deterioration.	One surface shrinkage crack; several inter-connected cracks.	Coarse aggregate particle is the only remains of core; limestone aggregate.	Coarse aggregate particle is the only remains of core; Dolomite aggregate.	Poorly compacted; poor aggregate.
AGGREGATE SOURCE	13012	13012 10072			10072	10072	21011
CONCRETE	None	Severe	Severe	Few	•		Severe
CRACKS ZE AGGREGATE W	Few	Severe	Severe	Few			Severe
CRA FREEZE THAW	No	Yes	Yes	No			Yes
SCALING	N O	Yes	O N	No			Yes
AGGREGATE TYPE	GR	GR	જ	જ	8	જ્ઞ	GR
AIR LIME	Yes Yes	*Yes No	*Yes Yes	*Yes No			No Yes
CORE	5-27	5-28	5-31	5-33	1-9	6-2	6-3

*Insufficient air entrainment for proper freeze-thaw protection.



TABLE 6, CONT.

CONTENTS	Dolomite coarse aggre- gate; excellent concrete.	Excessive parallel cracking.	Poor aggregate.	Extremely cracked limestone coarse aggregate.	Excessive parallel cracking; banded limestone coarse aggregate.	Banded limestone coarse aggregate; 4 bands of parallel cracks across top onehalf.	One surface shrinkage crack; one parallel crack near bottom.	Surface shrinkage cracks; good concrete.
AGGREGATE SOURCE		03052	03052	03012	03012	71012	71012	40032
CONCRETE	None	Severe	Severe	Severe	Severe	Severe	Moderate	None
CKS AGGREGATE	None	Severe	Severe	Severe	Severe	Severe	Moderate	None
CRACKS FREEZE AG THAW	No	Yes	Yes	Yes	Yes	Yes	Yes	No
SCALING	No	Yes	Yes	Yes	Yes	Yes	No	No
AIR LIME AGGREGATE TYPE	GR&CS	છ	જ	જ્ઞ	প্ত	છ	જ્ઞ	85
LIME	No	Yes	Yes	Yes	Yes	No	Yes	Yes
AIR	Yes No	No	No	No	No	No	No	No
CORE	6-5	<i>L</i> -9	6-11	6-14	6–15	6-17	6-18	6-21



TABLE 6, CONT.

COMMENTS	Excessive parallel cracking.	Very poorly compacted; parallel cracks through aggregate particles; large parallel crack near bottom.	Surface shrinkage cracks; poorly compacted; poor aggregate.	Few cracks except parallel surface cracks.
AGGREGATE SOURCE				
CONCRETE	Severe	Moderate	Moderate	Moderate
CRACKS FREEZE AGGREGATE THAW	Severe	Severe	Severe	None
CRACKS FREEZE AG THAW	Yes	Yes	No	No
SCALING	Yes	o N	ON O	Yes
AIR LINE AGGREGATE TYPE	જ	GR	શ	GR
LIME	Yes	Yes	Yes	Yes
AIR	No	No	No	S S
CORE	6-24T	6-25	6-26T	6-27

filing system identifying aggregate suppliers and their locations.

Analysis of variance was run on the test core physical condition microscope data to determine which variables significantly affect the blow-up distress of a concrete pavement. The analysis technique was individually to analyze the effect of two or three factors, each factor with two levels. Extreme values were selected for the levels of each factor. An unequal cell size two-way and three-way factorial analysis of variance was run on selected factor combinations.

Table 7 shows the factors and the factor levels analyzed for the test cores physical condition microscopic data. Concrete age, overlay thickness and source of coarse aggregate were also analyzed and are included in Table 7.

Table 8 shows a typical analysis of variance table for the statistical analysis of surface and aggregate type. This shows the type surface to be significantly different at the 0.01 level and no difference in aggregate type or the interaction of both factors. The cell means of the surface factor imply that overlaying a pavement increases the blow-up distress. The analysis of variance summary of all those factor combinations analyzed is shown in Table 9. Surface is the only factor which shows a significant difference.

All cell means of the surface factor show overlaying a pavement increases the blow-up distress.



TABLE 7

FACTOR LEVELS OF THE
TEST CORES PHYSICAL CONDITION

FACTOR	LEVEL ONE	LEVEL TWO
Surface	Bare	Overlayed
Air Entrainment	Yes	No
Lime Deposits	Yes	No
Aggregate Type	Gravel	Crushed Stone
Freeze-Thaw Cracks	Yes	No
Aggregate Cracks	Yes	No
Concrete Cracks	Yes	No
Concrete Condition	Excellent	Poor
Age	<21 years	>21 years
Total Overlay Thickness	<2 inches	>2 inches

TABLE 8
STATISTICAL ANALYSIS OF SURFACE AND AGGREGATE TYPE

SOURCE	DEGREES OF FREEDOM	SUMS OF SQUARES	MEAN SQUARES	F
Surface	1	822.60	822.62	*15.21
Aggregate Type	1	9.09	9.086	0.17
Interaction	1	13.72	13.72	0.25
Residual	88	4759.65	54.09	
Total	91	5605.08		


^{*}Significant at the 0.01 level.



TABLE 9

ANALYSIS OF VARIANCE SUMMARY

FACTORS ANALYZED B Air Entrainment	F. C. F.	FACTOR SIGNIFICANT AT THE 0.05 LEVEL Surface	F RATIO	F TEST
Lime Deposits		Surface	ري. ا ا	رد. د د د د د د د د د د د د د د د د د د د
Aggregate Type		Surface	15.21	3.96
Freeze-Thaw Cracks		Surface	2.67	3.95
Aggregate Cracks		Surface	12.29	3.96
Concrete Cracks		Surface	8.52	3.95
Concrete Condition		Surface	7.43	4.01
Concrete Condition	Concrete Age	Surface	6.53	4.06
Concrete Condition	Aggregate Type	Surface	12.80	4.06
Source of Coarse Aggregate		None		2
Aggregate Type		None		
Overlay Thickness		None		



Infiltration

Infiltration is suspected to be the main factor of the blow-up mechanism by some people. This hypothesis was investigated by coring joints and cracks. The general vicinity of a joint or crack, especially in a deteriorated pavement, is commonly more deteriorated than any other location, and difficulty in obtaining a good core was encountered. Many cores were taken at the location of a joint or crack only to find that the concrete was in such a deteriorated state that only rubble was obtained. The walls of the core hole crumbled and made it impossible to determine if infiltration was present except for the cases where it was excessive.

A reliable technique in obtaining a core over a joint or crack was to core through the top of a dowel bar. The dowel bar supplied rigidity to hold the concrete together while it was cored and removed. Special care must be taken during coring, because if the concrete semicircle crosssections slip and turn, the drill core will be destroyed. The cores were removed from the pavement, and the two sections were immediately taped together so that they would remain intact without loss of infiltration material until tested in the laboratory.

The cores were allowed to air dry in the laboratory before being opened and processed for testing. A technique was developed to determine quantitatively the amount of



infiltration present at a joint or crack. The procedure was to carefully separate the two sections of each core, apply a very thin coat of a wetting epoxy, carefully place the two pieces together exactly as they were originally and apply pressure to cause the excess epoxy to excrete before setting. Once hardened, sections were cut perpendicular to the joint or crack. These sections were then carefully polished and visually investigated under the microscope. This technique worked well and can be used to detect and quantitatively measure infiltration. Amount of infiltration was determined to 0.5 millimeters through the microscope by placing a scale near the area to be measured. The average values of infiltration determined by this method along with comments and test section information are given in Table 10.

Based on the infiltration analysis of the test cores, it is apparent that the top portion of a pavement is infiltrated by sand particles. This seems reasonable since it is common practice to apply a mixture of sand and de-icing compounds for snow and ice removal during the winter months when the joints are open.

Unlike the top portion, the lower portions of joints are commonly infiltrated by fine-grained soils. Pumping through joints and cracks is a common occurrence when subgrades and bases are composed of fine-grained soils and are wet. The presence of lime deposits was a common finding for most of the test cores visually analyzed under the



TABLE 10

INFILITRATION ANALYSIS OF TEST CORES

COMPENTS	Three distinct layers of sand on top portion and a fine grain soil on bottom, both held in place with asphalt.	A mixture of sand and fine grain soil, held in place with asphalt.	Pieces of concrete, aggregate particles and sand particles held in place by an excessive amount of asphalt. Severely cracked perpendicular to joint in vicinity of entrapped particles.	Many layers of fine grain soil, sand and asphalt.	Surface shows presences of scal- ing. Sand particles held in place with asphalt. Presence of cracks caused by particles visible.	Sand particles present on top one-half of joint with fine grain soil particles on bottom one-half of joint.
CORE	Joint	Joint	Joint	Joint	Joint	Crack
AVERAGE INFILTRATION In mm	7.0	5.0	0.8	12.7	3.0	2.0
BLON-UPS PER MILE	0.2	2.6	9.0	7.8	22.2	0.0
NUMBER OF OVERLAYS	5	1	ı	2	N	0
ROUIE	40	63	40	710	70	17
CORE	3-23	3-34	3-38	4-5	4-11	5-13

		soil.	icles alt.
	SIMENTIS	Small amount of fine grain soil.	Several layers of sand particles with a small amount of asphalt.
	CORE	Crack	Joint
	AVERAGE INFILTRATION in mm	0.5	η•0
	BLOW-UPS PER MILE	11.1	2.4
	NUMBER OF OVERLAYS	1	m
TABLE 10, CONT.	ROUTE	41	31
TABLE]	CORE	5-16	6-22

microscope as previously presented in Table 6. This implies that pavements are at one time or another in the presence of water since lime can be transported in solution only. Therefore the presence of fine-grained soil in the lower portion of the joints is due to pumping of subgrade and base fine-grained particles.

Both sand and fine-grained particles generally show a layered structure, which implies time dependence. This gives an indication of continuous infiltration growth which could explain the time dependence of blow-up distress as presented in the State blow-up survey (10).

Infiltration is compounded by the presence of asphalt.

Although compounds, usually asphalt based, are applied to protect and seal joints from water and infiltration, it is obvious that their presence adds to the infiltration problem by trapping particles which possibly could be removed by traffic or pumping.

The data of Table 10 were statistically analyzed to determine if a correlation exists between blow-up distress and infiltration. A R² value of 0.05 was found for the relationship, which indicates hardly any correlation.

The joint of a typical forty foot pavement must go through a range of contraction and expansion over the seasons of approximately 6 millimeters. If the pavement placement temperature was $70^{\circ}F$ and its shrinkage was 200×10^{-6} at $100^{\circ}F$, every joint would be open by 0.6



millimeters. Assuming Euler's column buckling theory and the above conditions apply, the total amount of incompressible infiltration required to cause a blow-up is 4 millimeters. Therefore any pavement with infiltration in excess of 4 millimeters would be expected to fail by buckling. This value is not in agreement with the test data. The heavily infiltrated test samples do not show the highest blow-up disturbance, and two of the least infiltrated test samples show the highest blow-up performance. This is in contradiction with what might be expected, but consideration must be given to the data analyzed. The blow-up distress was categorized by visual observation of the pavement's surface condition; past blow-up distress could have been repaired or covered by an overlay. The joint samples were difficult to obtain and no replicas exist for a given road. Therefore it was necessary to assume uniformity of infiltration within a section which most probably did not occur.

The number of samples in joints was insufficient to reach definite conclusions. Several points, however, do warrant comment. Many of the cores which were taken showed concrete was so badly deteriorated as to be essentially rubble. This condition invalidated the core for evaluating infiltration but provided valid input as to the condition of the concrete at the location of the blow-up.



Further overall inference as to the problem of infiltration can be made when considering the finding of the Statewide Survey of Blow-ups in Resurfaced Concrete Pavements, (10). Reduced infiltration from the bottom would be expected when granular bases were used. This may be one, but probably not the only reason, that such bases reduce blow-ups. Other reasons are better drainage and better pavement support hence reduced deflections under load. Surface infiltration is attributed largely to winter maintenance activities hence the greater occurrence of blow-ups in the northern districts is in agreement with the concept of infiltration stresses.

Infiltration most assuredly is not the only cause of blowups, but its occurrence can only aggravate the problem.

Thermal Expansion

A conclusion of the State blow-up survey (10) was that blow-up distress of overlayed concrete pavements made of gravel aggregate is higher than pavements made of crushed limestone aggregate. This implies that the coefficient of thermal expansion may be a significant factor in the blow-up mechanism because silicious materials have generally a higher coefficient of thermal expansion than carbonate




materials. To test this hypothesis, the coefficients of thermal expansion of selected test cores with known blow-up performance were determined.

A typical blow-up occurs between one and three o'clock in the afternoon on a hot day that was preceded by one or two days of heavy rainfall (1). This implies high temperature and moisture states are necessary for a blow-up to occur. The coefficient of thermal expansion is a function of moisture content, so consideration must be given to it as well as temperature in establishing the method of testing.

The field data given in Appendix D show the average daily temperature range within a pavement is $70^{\circ}F$ to $100^{\circ}F$ during the time a blow-up is most likely to occur. This was established as the temperature range to be used in determining the coefficient of thermal expansion of the test cores and laboratory prepared samples.

A 30°F temperature change corresponds to a length change of approximately 0.00060 inches for a sample length of 4 inches and a coefficient of thermal expansion of 5.0x10⁻⁶/°F. The length change measuring device must be capable of measuring, with sufficient accuracy and sensitivity, to 0.00003 inches or better in order to determine the coefficient of thermal expansion to 5 percent accuracy.



Linear Variable Differential Transformer

A linear variable differential transformer, hereafter referred to as an LVDT, was selected as the length change measuring device for the coefficient of thermal expansion apparatus. A Schaevitz type 050-HR S/N602-M LVDT was fitted with a teflon liner and meticulously honed to obtain a near perfect core fit. Two stainless steel counterweights, one above the LVDT and one below the LVDT, were used to obtain core balance. The core was indexed so that its radial position, relative to the LVDT, would remain constant during calibration and testing.

The primary coil of the LVDT was supplied an input of 3.0000 volts at 2500 hertz by an Exact Model M 7230 function generator. The output of the secondary coil was measured, unamplified, to the nearest 0.00001 volt with a digital voltmeter.

Sensitivity, accuracy and repeatibility were increased several orders of magnitude by the LVDT modifications and input-output techniques described above compared with conventional LVDT operational methods.

The LVDT was calibrated with a large barrel calibration micrometer capable of measuring to the nearest .00005 inches. The slope of deformation and voltage change was found to be 0.056 IN/VOLT. This corresponded to a sensitivity of 5.6x10⁻⁷ inches which was two orders of magnitude greater than required to confine the error to 5 percent.



Heating Chamber

The function of the heating chamber was to vary the temperature of the test sample. The heating chamber was designed so its dimensional changes would be independent of the test samples measured dimensional change.

The heating chamber is shown in Figure 42, and consists of a series of different sized cylinders mounted on a base of brass and plexiglas. The inner brass cylinder with inside diameter of 64 inches and 1/8 inch wall was welded to the 3/8 inch brass base plate which was attached to the bottom 3/4 inch plexiglas base by a series of screws. O-rings located between the two base plates assured against leakage when the chamber was full of water. The middle pyrex glass cylinder with outside diameter of 180 millimeters and 4 millimeters wall, wrapped with flat strip nichrome heater wire and overlayed with insulation tape to assure contact, rested atop an O-ring that was contained in a grooved slot in the base plate. The outer cylinder with outside diameter of 8½ inches and 1/8 inch wall was also welded to the brass base plate to assure rigidity. space between the middle and outer cylinder was filled with perlite to help minimize heat loss across the outer cylinder. A plexiglas 14 inch thick cap plate with three grooves, each containing O-rings, was held in place by a threaded plexiglas ring which screwed on to the threaded outer brass cylinder. Five holes through the cap plate provided access






FIGURE 42. DETAILS OF HEATING CHAMBER



for temperature sensors, a cooling coil and sample extension rod. The plexiglas base had two horizontally tapped holes which connected to a series of holes in the brass base plate. This allowed filling and draining of the heating chamber. The heater wire leads were routed through the brass base plate and out the side of the plexiglas base.

Temperature regulation was obtained by a Cole-Palmer Model 2157 temperature controller. The sensing probe was inserted through the top cap next to the wall of the inner brass cylinder. A variable voltage controller wired in series with the temperature controller supplied voltage to the heater coil and was therefore a means of varying the rate of temperature change within the heating chamber.

Tripod

The LVDT was suspended above the heating chamber by a special fused quartz tripod. Fused quartz tubing was precisely ground and epoxied together to form a tripod 14 inches high. The LVDT fitted inside the center fused quartz tube and was vertically aligned by three adjusting set screws which were held in place by three nuts epoxied at the middle of the tube.

Fused quartz was selected over other materials for construction of the LVDT tripod support because of its low coefficient of thermal expansion, $2.7 \text{x} 10^{-7} / ^{\circ} \text{F}$. It was imperative for the support to remain dimensionally stable during the testing period. A dimension change would be



erroneously recorded as a change in sample length. Special emphasis was placed on insulating the test chamber to minimize temperature change in the support tripod. The test chamber was completely enclosed by a one inch layer of Armstrong Armaflex foam insulation to minimize heat loss. Likewise, an additional precaution was taken to assure temperature stability, a small fan was placed near the test apparatus to maintain constant temperature. The temperature of the support tripod was therefore maintained at room temperature during the testing period. Although the room temperature of the laboratory is not controlled, it did not vary by more than five degrees during the testing time period. A temperature change of this magnitude, over the 14 inch high tripod, causes a dimensional change of 0.000019 inches which is readily measured by the LVDT system. Obviously the accuracy of the testing apparatus was limited by temperature stability and not by electronic sensitivity or stability. Nevertheless, the error involved by temperature stability was within the limits previously mentioned.

Sample Support and Extension Rod

Special consideration was given to the method of supporting the test sample because every change in dimension from the support base through the LVDT supporting tripod was measured by the LVDT. A special glass called ULE, and supplied by the Corning Glass Company, with a zero coefficient of thermal expansion within the temperature testing



range was used to prevent dimensional change caused by the method of specimen mounting. The centrally located base plate hole of the heating chamber was oversized to provide ample clearance for a one inch diameter ULE glass cylinder of variable height (dependent upon specimen height), to rest upon the support base. A ULE glass plate was placed atop the ULE glass cylinder and the test specimen atop this. Another ULE one inch diameter cylinder was placed on top of the test specimen with a fused quartz extension rod bonded to it by a thin layer of Eastman 910 contact cement. ends of the ULE glass cylinders and the fused quartz extension rods were ground parallel to within 0.001 inches to assure vertical alignment. The only measurement error possible in the mounting was due to the dimensional change of the short extension rod. The length of this sample extension rod was always minimized by using an optimum combination of various lengths of ULE glass. The length was kept to three inches or less. This length over a 30°F temperature change gives a dimensional change of 0.00002 inches. conservative value because the temperature change was not uniform throughout the three inch length and only the portion within the heating chamber would undergo the 30°F temperature change.

The total temperature stability error of calculating a coefficient of thermal expansion is a summation of the dimensional changes caused by a temperature change in the



LVDT supporting tripod and the sample extension rod. This summation is a maximum of 0.00004 inches which for a short sample of 4 inches represents an error of 5 percent. The error of measuring the temperature change as previously discussed in the field section and the error of the LVDT are both much less than the temperature stability error and do not significantly affect the total error.

The only other sources of error involved in this method of measuring the coefficient of thermal expansion is caused by the support base. The heating chamber, sample and LVDT supporting tripod were independently supported by the support base. Several materials were evaluated for the common support base. The optimum base was found to be the concrete floor of the laboratory. The error caused by the support base could not be quantitatively evaluated but is not expected to be significant. The low conductivities of the plexiglas and ULE glass along with the high mass of the concrete floor are in favor of little or no temperature change in the concrete floor. The effect of the support base was therefore not expected to have any influence on the total error of measurement. Therefore the maximum error possible by the testing apparatus was always smaller than 5 percent.

Testing Technique

Specimen preparation consisted of cutting the ends of a test core perpendicular to its longitudal axis and

duction in the description of the complete willing for a simple of the community of the com


smile Teaching

To alma on a contribution of contribution of the contribution of t

polishing each end until parallel within 0.01 inches, as measured by rotating the sample under an independently mounted dial gauge. The test specimen was then oven dried to constant weight at 105°C, brought to room temperature, and three thermocouples were attached to its side by a double layer of masking tape, one at its mid height and one one-half inch from each end.

The sample was then placed in the heating chamber, and the LVDT was vertically aligned. Upon temperature equilibrium among the three sample thermocouples and the LVDT input and output, the three temperatures were recorded, and the temperature controller was turned on. When the temperature of the test core sample was stabilized at approximately 100° F, the temperature controller was turned off, and a set of data points were recorded.

The time of test for the dry and wet tests varied from two to five hours, depending upon the size of the test specimen. The total time of heating was a function of the temperature variation as measured on the surface of the specimen. Temperature was maintained until a variation of 2.0°F or less between the top and bottom thermocouples was obtained. The heater was then turned off and the cooling period started. The temperature chamber was so efficiently insulated it was necessary to draw air through the test apparatus by means of an aspirator to cool the sample. When room temperature was obtained the aspirator was turned off,



and upon equilibrium of temperature, another complete set of data points were recorded. To assure repeatibility the above sequence was repeated so an average value of coefficient of thermal expansion could be calculated. One cycle of heating and cooling was completed in an average of eight hours.

The testing technique for the saturated case was to saturate the oven dried cores for twenty-four hours and then test them submerged under water in the heating chamber in the same manner as the dry testing technique. A copper cooling coil was placed inside the heating chamber and temperature was controlled by pumping ethylene glycol from a constant temperature bath. Occasionally the heating chamber was used as an auxillary heater to expedite the rate of heating.

Test Cores

The coefficient of thermal expansion was determined for the dry and wet moisture states for selected test cores in accordance with the previously outlined techniques. The data are shown in Table 11. Except for those coefficients noted, all are an average of two to five cycles of heating and cooling. These data are separated into heating and cooling temperature cycles to show the variation encountered in the coefficients of thermal expansion. The dry moisture state coefficients calculated from the positive and negative temperature changes were all individually within the 5



TABLE 11

APPARENT COEFFICIENT OF THERMAL EXPANSION OF TEST CORES / Fx106

FAGE COOLING AVERAGE HEATING COOLING COOLING COOLING COOLING AVERAGE HEATING COOLING 6.11 5.97 6.44 5.91 6.44 5.91 6.44 5.91 4.62 4.23 4.60 4.22 6.34 6.19 6.34 6.19 6.34 6.19 7.40 4.08 4.95 3.22 5.95 5.64 5.82 4.98 5.65 5.55 5.38 5.41 5.68 5.40 *5.37 7.65 5.55 6.38 5.40 *5.37 7.65 6.37 4.59 6.59 6.59 6.59 6.51	Į.		DRY			WET	
6.11 5.97 6.44 5.91 6.44 5.91 6.44 5.91 6.44 5.91 6.44 5.91 6.24 4.23 4.60 4.22 6.34 6.19 6.34 6.19 6.34 4.94 4.11 4.08 4.95 3.22 5.95 5.64 5.82 4.98 5.65 5.27 *5.68 5.40 *5.37 5.27 *5.61 *5.68 4.74 4.88 5.37 4.59 5.18 5.22 5.26 4.86 6.54 5.95 6.33 8.13 6.51	र्ज ६५	AVE HEATING	rg .	TOTAL AVERAGE	AVE HEATING	IRAGE COOLING	TOTAL
5.51 5.41 4.62 4.23 4.60 4.22 6.34 6.19 6.33 6.19 6.34 6.19 6.34 6.19 6.34 6.19 6.34 6.19 6.34 6.19 6.34 6.19 7.22 5.64 5.42 4.98 5.65 5.64 5.82 4.98 5.65 5.27 *5.68 4.74 4.88 5.41 5.68 6.24 5.25 6.33 5.95 6.24 5.95 6.33					6.11	5.97	40.9
5.51 5.41 4.62 4.23 4.60 4.22 6.34 6.19 6.23 5.24 4.94 4.11 4.08 4.95 3.22 5.95 5.64 5.82 4.98 5.65 5.55 5.27 *5.61 *5.68 4.74 4.88 5.27 *5.61 *5.68 5.18 5.22 5.26 4.86 6.524 5.95 6.33					44.9	5.91	6.18
5.23 6.34 6.19 6.34 6.19 6.34 6.19 6.24 5.42 4.94 4.11 4.08 4.95 3.22 5.95 5.64 5.82 4.98 5.65 5.55 5.68 5.40 *5.38 5.41 5.68 5.40 *5.37 4.59 5.27 *5.68 4.74 4.88 5.37 4.59 5.18 5.22 5.26 4.86 5.18 5.22 5.26 4.86 6.55 6.55 6.59		5.23	5.51	5.41	4.62	4.23	4.42
5.23 5.24 6.19 4.11 4.08 4.95 3.22 5.95 5.64 5.82 4.98 5.65 5.55 4.98 5.40 *5.38 5.41 5.68 5.40 *5.37 5.27 *5.68 4.59 4.74 4.88 5.22 5.26 4.86 5.18 5.22 5.26 4.86 5.95 6.24 5.95 6.59 5.95 6.51 8.13 6.51					4.60	4.22	4.41
5.23 5.24 5.42 4.94 4.11 4.08 4.95 3.22 5.95 5.64 5.82 4.98 5.65 5.55 4.98 5.40 *5.37 *5.61 *5.68 4.74 4.88 5.27 4.59 5.18 5.22 5.26 4.86 5.18 5.22 5.26 4.86 6.55 6.55 6.59 6.55 6.51					6.34	6.19	6.27
4.11 4.08 4.95 3.22 5.95 5.64 5.82 4.98 5.65 5.55 4.98 5.40 *5.37 *5.61 *5.68 4.74 4.88 5.27 *5.61 4.74 4.88 5.26 4.86 5.18 5.22 5.26 4.86 6.55 5.59 6.54 5.59 5.95 6.51 8.13 6.51		5.27	5.23	5.24	5.45	4.94	5.18
5.95 5.64 5.82 4.98 5.65 5.55 4.98 *5.37 *5.61 *5.68 4.74 4.88 5.37 4.59 5.18 5.22 5.26 4.86 5.95 6.54 5.95 6.59 5.95 6.51 8.13 6.51		η.06	4.11	4.08	4.95	3.22	4.14
5.65 5.41 5.68 5.40 *5.37 *5.61 *5.68 4.74 4.88 5.37 4.59 5.18 5.22 5.26 4.86 5.95 6.55 5.59 5.95 6.33 8.13 6.51		5.34	5.95	5.64	5.82	4.98	5.40
5.43 5.41 5.68 5.40 5.16 *5.37 *5.68 5.68 5.01 4.74 4.88 5.37 4.59 5.30 5.18 5.22 5.26 4.86 5.30 5.18 5.22 5.59 6.51 6.54 5.95 6.33 8.13 6.51		*5.36	5.65	5.55			
5.16 *5.37 *5.61 *5.68 5.01 4.74 4.88 5.37 4.59 5.30 5.18 5.22 5.26 4.86 6.30 6.59 6.59 6.59 5.71 5.95 6.24 5.95 6.33 8.13 6.51		5.43	5.38	5.41	5.68	5.40	5.57
5.01 4.74 4.88 5.37 4.59 5.30 5.18 5.22 5.26 4.86 6.55 5.59 5.71 5.95 6.33 8.13 6.51		*5.16	*5.37	5.27	*5.61	*5.68	5.65
5.30 5.18 5.22 5.26 4.86 6.59 6.59 6.33 6.51 8.13 6.51		5.01	4.74	4.88	5.37	4.59	4.98
6.55 6.55 5.59 5.95 6.24 5.95 6.33 8.13 6.51		*5.30	5.18	5.22	5.26	4.86	5.06
5.95 6.24 5.95 6.33 8.13 6.51					6.55	5.59	6.07
6.51		5.71	5.95	6.24	5.95	6.33	6.18
					8.13	6.51	7.32


*Coefficient determined over one heating cycle or one cooling cycle.



percent accuracy range previously discussed. The wet coefficients however show a difference between the heating and cooling cycles in excess of the 5 percent maximum error. The general trend is for the coefficient calculated from the heating cycle to be larger than the coefficient calculated from the cooling cycle.

The variation in the wet coefficients can be explained in terms of hygrothermal shrinkage and swelling as defined by Powers (27) and Helmuth (20). When the temperature of a paste is increased the free energy of the water in capillary pores decreases more than that of the water in the gel pores. This energy difference, caused by increasing the temperature, is eliminated by diffusion of gel water into the capillary pores. Removal of gel water causes a shrinkage. Decreasing the temperature causes a swelling by diffusion of capillary water into the gel pores.

This hygrothermal effect was shown to be time dependent. When the temperature change takes place slowly a state of equilibrium is maintained in the transfer of capillary and gel water and the hygrothermal effect is eliminated. Increased rates of temperature change induce a lag in the transfer of water and cause a portion of the total length change to be time dependent. Given sufficient time at constant temperature this portion of the length change is eliminated. Since insufficient time was allowed for equilibrium in the testing procedure the effect of



hygrothermal shrinkage and swelling was compounded in the apparent coefficient of thermal expansion. The end result would appear as an increase in the coefficient of thermal expansion for a positive temperature change and a decrease in the coefficient of thermal expansion for a negative temperature change thus explaining the differences.

The data of Table 11 were statistically analyzed to evaluate the effect of coefficient of thermal expansion on blow-up distress. The analysis showed coefficient of thermal expansion was not related to the blow-up distress of the pavements from which the test cores were obtained.

Moisture Expansion

Concrete placed in the presence of moisture or air at a higher relative humidity will expand or swell. The maximum swelling is approximately two-thirds of the original shrinkage the concrete has undergone (30). For the usual range of concretes the irreversible part of the shrinkage represents between 0.3 and 0.6 of the drying shrinkage, the lower value being more common. The magnitude of swelling and shrinkage vary with the range of moisture or humidity and composition of the concrete. The irreversible portion can be explained in terms of increased bonding between solids and a collapsing of the gel structure.

Dimensional changes caused by changes in moisture content are often referred to as "moisture movement" but will be considered here as moisture expansion. The possibility



of this dimensional change being highly related to the blowup mechanism is apparent when consideration is given to the
moisture state that must exist for a blow-up to occur. The
total magnitude of moisture expansion obviously could be an
important factor. The rate at which moisture expansion can
occur could also be significant. To examine these hypotheses, a test was devised to obtain moisture expansion data on
selected test cores with known blow-up distress.

Test Cores

The technique was similar to that of the test for coefficient of thermal expansion except that temperature was held constant and moisture content was varied. Moisture expansion was monitored as a function of time. The test set—up was similar to the coefficient of thermal expansion testing apparatus. Water was added to the test chamber after initial LVDT readings were recorded on the oven dried test cores. When the water level reached the base of the test sample the time was recorded. Temperatures were recorded from three thermocouples mounted in the water next to the test core. The initial temperature was recorded when the water reached the top of the test core. Data were taken at various time intervals over a period of at least twenty-four hours.

The moisture expansions occurring after twenty-four hours and forty-eight hours of submersion in water were selected for correlation with blow-up distress. These time



periods were selected because blow-ups occur during periods of high precipitation when pavements moisture contents are already high.

The data were corrected for temperature variation by using the "wet" coefficients of thermal expansions. The best fit power curve equation,

$$y = ax^b$$

where y is the moisture expansion in micro-strains, x is the time in hours and a and b are constants, was determined over the range of the twenty-four to forty-eight hour expansion data. The power curve equation was found to reliably describe the data. The regression coefficients and predicted moisture expansions of twenty-four hours and forty-eight hours are given in Table 12. The difference in these moisture expansions gives an indication of the amount of expansion which might occur per day after one day of saturation.

Stepwise regression was run on the wet coefficient of thermal expansion data and the moisture expansion data to determine the relation with blow-up distress. The most significant variable, explaining 32 percent of the variation, was the twenty-four hour moisture expansion. The second most significant variable was the "wet" coefficient of thermal expansion determined over a heating cycle. The R² value for these two variables was 0.48. The third most significant variable was the forty-eight hour moisture



TABLE 12

MOISTURE EXPANSION OF TEST CORES

TEST	REGRESSION	COEFFICIENTS	R^2	MOISTURE EX	(PANSION
CORE	a	Ъ		y = ax ^b MICRO-STRAINS	
				x=24 hrs.	x=48 hrs.
115	219.5	0.12	1.00	325.3	354.5
201	199.6	0.21	0.98	394.4	457.5
204	116.0	0.26	0.96	265.1	317.4
206	98.4	0.23	1.00	203.6	238.5
215	162.1	0.22	0.93	328.9	383.7
304	74.7	0.31	0.96	199.2	246.7
324	36.5	0.48	1.00	168.3	234.9
328	94.8	0.16	0.99	155.3	172.9
330	103.3	0.19	1.00	189.3	216.1
332	72.4	0.23	0.99	148.2	173.2
346	105.3	0.20	1.00	201.5	232.2
347	127.6	0.19	0.98	236.8	270.9
348	18.3	0.42	0.97	69.5	92.9
418	428.1	0.03	1.00	469.9	479.5
419	280.2	0.07	1.00	351.0	368.7

expansion with a combined R² value of 0.58. The difference between the forty-eight hour and twenty-four hour moisture expansion and the coefficient of thermal expansion based on the negative temperature change were not found to be significant. Analysis of variance of the data showed the twenty-four hour moisture expansion, wet coefficient of thermal expansion determined over a heating cycle, and forty-eight hour moisture expansion to be significantly related to a pavement's blow-up distress at the 0.05 level.

expansion with a compansor of years of 0.58. The difference between the forty-early four and twenty-four doubt moderance expansion and the coefficient of thomas expansion based on the moderation and the coefficient of thomas expansion based on the metalic four four four four and the coefficient of the coefficient of

SUMMARY

This research was conducted with two primary objectives, first to determine if overlaying a concrete pavement significantly influences blow-up performance, and second, to isolate those variables that affect blow-up distress.

The findings of this study are based upon the results of the field testing of a bare pavement and an overlayed pavement and the laboratory testing of pavement cores taken from various Indiana highway pavements.

The following summarize the findings of this report.

Field Testing

- 1. Moisture gauges were successfully developed and used to evaluate the moisture contents of a bare pavement and an overlayed pavement.
- 2. The overlayed pavement, for any given vertical position, always had a higher degree of saturation than that of the bare pavement.
- 3. The overlayed pavement holds moisture and did not dry out as readily as the bare pavement and therefore showed a smaller variation of degree of saturation with time.



- 4. Vertical moisture gradients were always present in the overlayed pavement. In general the degree of saturation increased from the top to the bottom of the pavement.

 Except for the winter season the bare pavement had an approximately constant degree of saturation throughout its depth.
- 5. Both pavements surpassed the level of critical saturation for freezing and thawing damage during the test period. The overlayed pavement obtained this critical level during the winter months whereas the bare pavement did not obtain this level until late spring when freezing temperatures were no longer present.
- 6. Horizontal moisture gradients were a function of the season. Through late winter the overlayed pavement's average degree of saturation increased horizontally from its side to its middle at the rate of approximately 5 percent per foot. During the spring the average degrees of saturation of the pavement's side and middle were approximately equal and higher than the intermediate area between them. This horizontal moisture gradient was also about 5 percent per foot.
- 7. The time required for a significant change in the moisture state of the overlayed pavement was a function of precipitation. The overlayed pavement had a degree of saturation approximately 13 percent higher than the bare pavement to date.
- 8. The ball system was capable of measuring horizontal and vertical pavement deformations.



- 9. The overall seasonal trend of deformation, based on the original lengths, was for the overlayed pavement to always show an expansion while the bare pavement tends to show a slight contraction. The maximum difference in deformation between the two pavements corresponded to a temperature change of about 10 degrees and occurred during the summer months when blow-ups are prevalent.
- 10. The average degree of saturation of the pavements and their deformations responded directly with extended dry periods and precipitation in excess of one inch.
- 11. Overlaying a pavement increased its degree of saturation and decreased its coefficient of thermal expansion.
- 12. The slope of the thermal coefficient of thermal expansion and degree of saturation curve over the normal range of moisture encountered in the field was about $-0.018/^{\circ}F/\%$ degree of saturation.

Laboratory Testing of Pavement Cores

- 1. Laboratory equipment were devised to determine the coefficient of thermal expansion of test cores within an accuracy of 5 percent.
- 2. Analysis of variance showed a significant difference in the blow-up performance for the type of surface the overlayed pavements showing the greater blow up occurrence



- 3. Twenty-four hour moisture expansion, wet coefficient of thermal expansion and forty-eight hour expansion analyzed together were shown to be significantly related to a pavement's blow-up distress at the 0.05 level. It is interesting to note that coefficient of thermal expansion when analyzed alone was not significantly related to blow-up distress. This showed the complex interaction that must exist between temperature and moisture. Although such an interaction exists, regression analysis did not show a high correlation ($\mathbb{R}^2 = 0.58$).
- 4. Infiltration did not relate highly to blow-up distress, for the tested joint cores.
- 5. The "wet" coefficient of thermal expansion determined over a heating cycle were significantly larger than the coefficients of thermal expansion determined over a cooling cycle.



CONCLUSIONS

The following conclusions seem reasonable and are based on the results of the field test pavement and the laboratory testing of test cores.

- 1. Overlaying a concrete pavement causes its degree of saturation to increase and a corresponding moisture expansion occurs.
- 2. An overlayed concrete pavement becomes critically saturated with respect to freezing and thawing durability during the winter season.
- 3. Seasonal variation of moisture content is reduced by overlaying a concrete pavement.
- 4. Vertical moisture gradients always exist in the overlayed pavement. In general the degree of saturation increases from the top to the bottom of the pavement. Except for the winter season the bare pavement shows an approximately constant degree of saturation throughout its depth.
- 5. The coefficient of thermal expansion is reduced slightly, but probably not significantly, by overlaying a concrete pavement.



- 6. The blow-up distress of an overlayed pavement is significantly greater than the blow-up distress of a bare pavement.
- 7. Blow-up distress is related to moisture expansion and coefficient of thermal expansion by some complex interaction.
- 8. Infiltration commonly found in pavement joints consists of sand particles on the top and fine grained soil particles on the bottom held in place by asphalt sealants.
- 9. Infiltration cannot be demonstrated to be significantly related to blow-up distress.



CONCLUDING COMMENTARY

Blow-ups in bituminous overlaid rigid pavements were found to increase with the age of the pavements. Several reasons for this have been previously elaborated upon but little has been said concerning ways of alleviating the problem.

Obviously forces develop within the pavement causing the pavement to fault or crush. The latter is more probable in older pavements which includes most overlays. The result is a hump but it is generally not nearly as abrupt as that caused in newer pavements by faulting or even fracturing (crushing) of quality concrete.

When crushing, (fracturing) occurs the bulk volume of the concrete increases and horizontal stress relief is accomplished by further displacement of the material. The result is the formation of a hump beneath a pavement. This could occur slowly over a period of months or years. If the volume of crushed material is small the height of the bump may be larger as well as more abrupt because all of the horizontal relief is accommodated within the relative small distance of the blow-up. If a larger area were broken the height and abruptness of the bump would presumably be less.

It follows then that relief regions could be provided.

This is done in many instances by removing portions of the pavement and replacing with bituminous material. An alternative



which would perhaps insure better continuity in the pavement, especially if it is a reinforced pavement would be to break up, but leave in place, portions of the rigid pavement in transverse section across the pavements. Resurfacing or patching would then cover the section.

To the knowledge of the principal investigators, this approach has not been intentionally done on a pavement. It is suggested that when blow-ups are occurring beneath an overlay, or when the bare concrete pavement shows evidence of concrete deterioration adjacent to joints or transverse cracks, the following be tried on an experimental basis:

By means of mechanical hammer break up concrete for at least three feet on each side of the joint or crack, resulting in a broken pavement section at least six feet in length. The break up should be most severe in the center of the six feet section. All material should be left in place. Patching or resurfacing should then be done to restore a smooth surface.

Such sections should be located at a frequency depending upon judgement of the severity of the pavement deterioration or possible future deterioration. For an old deteriorated pavement the spacing might be every 40 feet, while in a relative new pavement, 100 feet or more might suffice.

LIST OF REFERENCES



LIST OF REFERENCES

- 1. "Repair of Concrete Blowups in Delaware", Engineering News-Record V. 95, v. 11, p. 432, September 1925.
- 2. Woods, K. B., Sweet, H. S., and Shelburne, T. E., "Pavement Blowups Correlated with Source of Coarse Aggregate", Proceedings, Highway Research Board, Vol. 25, 1945.
- 3. Graham, M. D., Chamberlin, W. P., "Summary of 1966 Rigid Pavement Blowup Survey", Unpublished Report, Engineering Research and Development Bureau, New York State Department of Transportation.
- 4. Hensley, M. J., "The Study of Pavement Blowups", Research Project 10, Arkansas State Highway Department, January, 1966.
- 5. Illinois Division of Highways, "A Study of Blowups in Rigid Pavements in Illinois", Research and Development Report 18.
- 6. Stott, J. P. and Brook, K. M., "Report of a Visit to U. S. A. to Study Blowups in Concrete Roads", RRL Report LR 128, British Ministry of Transport, 1968.
- 7. Moyer, R. A., "An Eleven-year Study of the Expansion and Contraction of a Section of Concrete Pavement", Proceedings, Highway Research Board, Vol. 25, p. 71, 1945.
- 8. Regel, F. V. and Gotham, "Field Observation on Effects of Joints on Cracking and Other Deterioration in Concrete Pavements", Proceedings, Highway Research Board, Vol. 21, p. 179, 1941.
- 9. Spangler, M. G., "Stresses in the Corner Region of Concrete Pavements", Iowa Engineering Experiment Station Bulletin 157, 1942.
- 10. Foxworthy, P. T., "Statewide Survey of Blow-ups in Resurfaced Concrete Pavements", Master Thesis, Purdue University, May, 1973. (Also Interim Report, JHRP-73-3, February 1973).

- 11. Lu, N. Y., "Comparison of the Thermal and Moisture Expansion of Concrete", Master Thesis, Purdue University, February, 1948.
- 12. Meyers, S. L., "Thermal Expansion Characteristics of Hardened Cement Paste and of Concrete", Proceedings, Highway Research Board, Vol. 30, pp. 193-203, 1950.
- 13. Mitchell, L. J., "Thermal Expansion Tests on Aggregate, Neat Cements and Concretes", Proceedings, American Society of Testing and Materials, Vol. 53, p. 963, 1950.
- 14. Teller, L. W., and Sutherland, E. C., "Observed Effects of Variations in Temperature and Moisture on the Size, Shape, and Stress Resistance of Concrete Pavement Slabs", Public Roads, Vol. 16, No. 9, November, 1935.
- 15. Hatt, W. K., "The Effect of Moisture on Concrete", Transactions, American Society of Civil Engineers, 89:270, 1926.
- 16. Scholer, C. H., "Factors Affecting Volume Changes in Concrete and Their Significance in Design", Proceedings, Highway Research Board, Vol. 11, pp. 240-261, 1932.
- 17. Myers, B., "Volume Changes in Concrete Slabs in the Field", Proceedings, Highway Research Board, Vol. 11, 1932, pp. 262-270.
- 18. Davis, R. E., "A Summary of Investigations of Volume Changes in Cements Mortars and Concretes Produced by Causes Other than Stress", Proceedings, American Society of Testing Materials, 668-85, 1930.
- 19. Dawley, E. R., "Volume Changes of an Early-Strength Concrete", Proceedings, American Society of Testing and Materials, Vol. 32, p. 642, 1932.
- 20. Helmuth, R. A., "Dimensional Changes of Hardened Portland Cement Pastes Caused by Temperature Changes", Proceedings, Highway Research Board, Vol. 40, 315-336, 1961.
- 21. Gordinier, D. E. and Chamberlin, W. P., "Pressure Relief Joints for Rigid Pavements", Research Report 68-12, Engineering Research and Development Bureau, New York State Department of Transportation.
- 22. Lewis, D. W., "The Performance of Concrete Resurfacing in Indiana", Proceedings, Highway Research Board, Vol. 50, December, 1950.



- 23. Gotham, D. E. and Lord, G. W., "Concrete Resurfacing of Concrete Pavement in Various Stages of Deterioration", <u>Bulletin</u> No. 87, Highway Research Board, 1954.
- 24. Ballard, L. F., "Instrumentation for Moisture Measurement", NCHRP Project 21-1, July, 1971.
- 25. Lentz, A. E. and Monfore, G. E.", Thermal Conductivity of Concrete at Very Low Temperatures", Bulletin No. 182, Research and Development Laboratories of the Portland Cement Association, May, 1965.
- 26. Klieger, P., Monfore, G., Stark, D., and Feske, W., "D-Cracking of Concrete Pavements in Ohio", Portland Cement Association, October, 1974.
- 27. Powers, T. C., "The Physical Structure and Engineering Properties of Concrete", Bulletin No. 90, Research and Development Laboratories of the Portland Cement Association, July, 1958.
- 28. Powers, T. C. and Brownyard, T. L., "Studies of the Physical Properties of Hardened Portland Cement Paste", Bulletin No. 22, Research and Development Laboratories of the Portland Cement Association, March, 1948.
- 29. American Society of Testing Materials Standard Specifications C457, 1967.
- 30. Neville, A. M., <u>Properties of Concrete</u>, John Wiley and Sons, Second Edition, 1973.
- 31. Kingery, W. D., Introduction to Ceramics, Wiley.



NOTICE

The following Appendices listed in the Table of Contents of this Report have not been included in this copy of the Report.

Appendix No.	<u>Title</u>	Pages
Α	Field Testing Error of Measurement	128-139
В	Moisture Gauge Design	140-153
С	Moisture Probe Calibration Data and Regression Analysis	154-159
D	Field Data	160-166
E	Cherry Lane Moisture Data	167-173
F	Daily Precipitation	174-176
G	Test Core Information	177-181

A recipient of the Report may secure a copy of the Appendix or Appendices desired upon request to:

Joint Highway Research Project Civil Engineering Building Purdue University W. Lafayette, Indiana 47907

~		



